

# SERVICE BULLETIN



M-1133

March 4, 2003

## 2003 SPORTSTER SERVICE MANUAL UPDATE

### Purpose

The purpose of this service bulletin is to inform you that the 2003 Sportster Service Manual (Part No. 99484-03) incorrectly described the rear belt deflection adjustment procedure.

### Motorcycles Affected

All 2003 Sportster models.

### Required Dealer Action

See INSPECTION, under Section 1.13, REAR BELT DEFLECTION (page 1-25). The second bullet point under "When checking belt deflection:" incorrectly states "Measure belt deflection with motorcycle cold and the approximate weight of the owner on motorcycle."

That sentence should read "Measure belt deflection with no rider or cargo on motorcycle, transmission in neutral, belt and sprockets at ambient temperature (cold engine), and motorcycle resting on side stand."

Mark all copies of this service manual and inform all dealer technicians of this update.

#### IMPORTANT NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO.1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	TECHNICIAN NO. 4	RETURN THIS TO
INITIAL HERE									

©2003 HARLEY-DAVIDSON MOTOR COMPANY