SERVICE BULLETIN

M1619: DIAGNOSTIC TROUBLE CODE (DTC) U04438F AND U04318F

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2023-12-18	-	Initial release

Purpose for Service Bulletin

This bulletin informs dealers that the current software version for the Left Hand Control Module (LHCM) and Right Hand Control Module (RHCM) have Diagnostic Trouble Codes (DTCs) U04438F (reported by the LHCM) and U04318F (reported by the RHCM), that are being set-off intermittently, shortly after a starting event and then seen as historic DTCs but there are no actual faults or operational concerns with the vehicle.

In these cases where these codes are being found as historic, no further troubleshooting or hardware replacement should take place to resolve these historic DTCs. This will be addressed in a future software release.

NOTE

If DTCs U04438F or U04318F are found to be CURRENT, follow troubleshooting steps in the Electrical Diagnostic Manual (EDM).

Current affected software levels:

- LHCM: 0.33.02
- RHCM: 0.37.02

Vehicles Affected

2021-2023: Pan America (RA1250/S), Sportster S (RH1250S), Nightster (RH975S)

Markets Affected

All markets affected.

Part Numbers

Refer to Table 2.

Table 2. Affected Part Numbers

Affected Part No.	Item Description
71500522	LHCM
71500536	LHCM

Table 2. Affected Part Numbers

Affected Part No.	Item Description
71500523	RHCM
71500541	RHCM

Required Dealer Action

Table 3.

Action Required	Resolution
NO ☑ YES ☐	**Non-Actionable:** This is for informational purposes only or a technical tip.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									