

BATTERY SUPPORT BRACKET / EARLY 1974 FL, FLH-1200

All 1974 FL, FLH-1200 models produced before December 14, 1973 should be checked for interference between the battery support bracket and bottom of battery.

If insufficient clearance exists, the battery can be damaged resulting in acid damage to the motorcycle.

Remove bracket from motorcycle, cut off corner as shown in diagram, and reinstall bracket on motorcycle.

