

# SERVICE BULLETIN



M-915

November 5, 1985

## 1986 XLH MODELS SERVICE MANUAL AND PARTS CATALOG MICROFICHE CORRECTIONS

### General

The 1986 XLH Models Service Manual, Part No. 99484-86, and the Parts Catalog Microfiche, Part No. 99451-86M both have errors. Please take the following action for correction of these errors:

### SERVICE MANUAL ERROR

Please mark the dealership manuals and inform customers who buy this manual to make the following corrections:

On page 6-30 in the "COUNTERSHAFT END PLAY THRUST WASHER CHART" make the following correction:

### COUNTERSHAFT END PLAY THRUST WASHER CHART

If End Play is (in.)	Install Thrust Washer	
	Quantity	Part Number
0.087 - 0.091	2	35863-86
0.082 - 0.086	2	35863-86
	1	35864-86
0.077 - 0.081	2	35864-86

Should be 1.

### PARTS CATALOG MICROFICHE ERROR

On page three, Grid Location A3, of the Parts Catalog Microfiche, the "NAME" and "USED ON" information for Part No. 16446-86 and 16447-86 have been transposed. That is, Part No. 16446-86 is for 883cc cylinders and pistons; Part No. 16447-86 is for 1100cc cylinders and pistons.

You may wish to display this correction on your Microfiche viewer.

ROUTING:	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	CHIEF MECHANIC	MECHANIC NO. 1	MECHANIC NO. 2	MECHANIC NO. 3	MECHANIC NO. 4	RETURN THIS TO:
INITIAL HERE									