# SERVICE BULLETIN



M-1434 2016-10-10

#### M-1434: J06225 CHOPPED ENGINE GUARD INSTRUCTION SHEET CORRECTION

## **Purpose**

The purpose of this bulletin is to inform dealers of a correction to the torque value when installing the Chopped Engine Guards. Products with a package date of 9/13/16 and earlier contain an Instruction Sheet with the incorrect torque.

#### Overview

· Kits required: No.

- Affected components: Chopped Engine Guard kits 49000105, 49000117, 49000114.
- Solution: Replace instruction sheet in affected kits.

#### Issue

The instruction sheet in Chopped Engine Guard kits 49000105, 49000117, 49000114 packaged on September 13, 2016 and earlier contain an incorrect torque value for the top mount screws. The correct torque value is 10.8–12.2 N·m (96–108 in-lbs).

#### Markets Affected

All markets are affected.

### **Required Dealer Action**

When installing the Chopped Engine Guard, follow the latest Instruction Sheet (J06225) with a torque value for the top mount screws of 10.8–12.2 N·m (96–108 in-lbs).

## **Dealer Inventory**

- Inspect the package date on the above referenced kits in dealer inventory.
- The updated instruction sheet (J06225) can be found on the Service Information Portal. Replace the instruction sheet in all kits packaged on September 13, 2016 or earlier with a copy of the latest instruction sheet.
- 3. Destroy the original instruction sheet.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE			17 5						