SERVICE BULLETIN



M1525 2021-05-03

M1525: 2021 PAN AMERICA - FAIRING LOWER RUNNING CHANGE

Purpose for Service Bulletin

Is to inform dealers that there has been a running change to the 2021 Pan America fairing lowers. The only service replacements offered are the revised version of the fairing lowers. If a cosmetic issue is discovered during Predelivery Inspection (PDI), order and replace both left and right fairing lower components. The replacement of both components only applies to vehicles built before the running change.

Motorcycles Affected

2021 Pan America

Markets Affected

All markets are affected.

Part Numbers

Table 1. Part Numbers

Part No.		Item Description					
5710034	18A F	FAIRING LOWER, right, water cooler, outlet					
5710034	19A F	FAIRING LOWER, left, water cooler, outlet					

Required Dealer Action

If a cosmetic issue is discovered to the lower fairings at PDI, or a warrantable issue is seen during the warranty period, then replace both left and right side components. File the appropriate warranty claim. If one of the lower fairings is replaced as a non-warrantable concern, replacement of the opposite side would be non-warrantable as well.

Return Parts

Hold all claimed parts for 60 d from date of credit issued for possible field inspection and/or request to return to factory. After 60 d, destroy and discard the parts.




Figure 1. Pan America Running Change (Right Shown, Left Similar)

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									