SERVICE BULLETIN



M1554 2022-07-05

M1554: 2022 FLTRK, FLHTK, FLHTP - HEATED GRIP SUBSTITUTION

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Revision Description			
2022-07-05	Initial release			

Purpose for Service Bulletin

This bulletin informs dealers that Harley-Davidson will have a certain number of 2022 Touring and Police models built with substituted heated hand grips. Refer to Table 2.

These heated hand grips are an approved substitution and no action should be taken to replace the substitute heated hand grips with the original part numbers. Refer to Table 3.

Motorcycles Affected

Table 2.

Year	Platform	Model
	Touring	FLHTK
2022	louring	FLTRK
	Police	FLHTP

Markets Affected

All markets are affected.

Part Numbers

Table 3. Part Numbers

Original Part No.	Item Description	Substitute Part No. #1	Substitute Part No. #2		
56209-10A	Left Hand (LH) Heated Grip	56100382	56100338		
56249-10	Right Hand (RH) Heated Grip	56100380	56100339		
56250-10	RH End Cap	56100385	56100337		

Required Dealer Action

The part substitutions noted in Table 3 are approved substitutions for the vehicle's configuration.

If the Dealer received a vehicle with the substituted parts, DO NOT order the original configured parts and DO NOT file a warranty claim for these parts at the time of delivery unless a defect or damage is found.

If at any time, during the vehicles warranty the substituted part fails, the substituted part must be ordered and replaced. Refer to Table 3.

-	in the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is prought into your dealership for either maintenance of service.									
	ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
	INITIAL HERE									