# **SERVICE BULLETIN**



#### M1556

## M1556: BUTTON/COIN BATTERY WARNING LABELS

## **Reason for Revision**

Refer to Table 1.

#### **Table 1. Document History**

	•
Date	Revision Description
2022-07-11	Initial release

## **Purpose for Service Bulletin**

This bulletin informs dealers that Harley-Davidson has components containing button or coin cell batteries supplied to Australia.

Harley-Davidson must comply with the applicable Australian mandatory safety and information standards. This requires adding warning labels to packaging that currently exists in dealer inventory in order to make them compliant.

## **Markets Affected**

Australia.

### **Part Numbers**

Refer to Table 2.

#### Table 2. Part Numbers

Item Description	Part Numbers		
	68926-00, 66373-06, 63002-		
	09A, 63004-09A, 63030-09A,		
	63055-09A, 63065-09A,		
	62955-09A, 68927-00, 68939-		
	00, 68200-07A, 68207-07A,		
	69995-11, 91684-08A,		
Components with Button or	41000021C, 41000021G,		
Coin Cell Batteries	41000087F, 41000460,		
	68000217, 68000218,		
	90300112, 90300146,		
	90300159, 90300160,		
	90300111, 90300117,		
	90300118, 91800066,		
	90300153, 90300156		

## **Required Dealer Action**

NOTE Warning Labels are automatically being shipped to dealership. If additional Warning Labels are needed, contact: Dealer Service Desk / DHL

dhl.harley-davidson.customerservice@dhl.com

Table 3	3
---------	---

Action Required	Resolution
	Actionable:
YES	Any vehicle, component or software related issues must be performed per service bulletin procedure.

1. Inspect inventory of Part Numbers. Refer to Table 2.

## **Dealer Inventory Instructions**

#### NOTE

Warning Labels must be installed to FOB ring and applied to packaging prior to being sold to consumer.

#### FOB

- 1. Inspect unsold vehicles. Make sure that the Hang Tag Warning Label is on the FOB.
- 2. See Figure 1. Packaging Warning Label (Part No. 14003753 / PKG202343).
  - a. Must have Warning Label applied to the outside of the package.
- 3. See Figure 2. Hang Tag Warning Label (Part No. 14003754 / PKG202340).
  - a. FOB must have Warning Label installed to FOB ring.
- 4. See Figure 3. FOB with Hang Tag Warning Label (Part No. 14003754) inside the factory packaging.
- 5. See Figure 4. FOB with Packaging Warning Label (Part No. 14003753) **applied to the factory packaging**.
- 6. See Figure 5. FOB (2) contents removed from factory packaging.
  - a. Install Hang Tag Warning Label (1) to FOB ring (3).

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									

2022-07-11



Figure 1. Package Warning Label 14003753




Figure 2. FOB Hang Tag Warning Label 14003754



Figure 3. FOB With Hang Tag Warning Label



Figure 4. FOB With Package Warning Label



Figure 5. FOB With Hang Tag

## Parts and Accessory Packaging

- 1. See Figure 1. Packaging Warning Label (Part No. 14003753 / PKG202343).
  - a. Must have Warning Label applied to the outside of the package.
- See Figure 6. Parts and Accessory packaging must have Warning Label (Part No. 14003753 / PKG202343) applied to:
  - a. Front of package in clear view.
  - b. Upper right hand corner.



Figure 6. Box With Package Warning Label 14003753

## **Credit Procedure**

NOTE

Enter bulletin number M1556 into Comment section of claim.

For **vehicles** in dealer inventory or registered as dealer demos, submit a claim per Table 4.

## Table 4.

ITEM	DATA
Claim Type	PDI claim or Stand-
	ard claim
Problem Part Number	Refer to Table 2.
Labour Code	8888
Labour Hours	0.1 h
Customer Concern Code	9203
Condition Code	9101

NOTE

Enter bulletin number M1556 into Comment section of claim.

For kits from Table 2 that are in dealer inventory, submit a claim per Table 5.

Table 5.

ITEM	DATA
Claim Type	PAM stock
Problem Part Number	Refer to Table 2.
Labour Code	8888
Labour Hours	0.1 h
Customer Concern Code	9203
Condition Code	9101