

# Table of Contents

<b>EVO: Oiling &amp; Lubrication - Sub-04I</b> .....	3
<b>Pics and Information on 2014-2022 Sportster Oil Tanks</b> .....	3



[Go To Technical Menu](#)

## EVO: Oiling & Lubrication - Sub-041

### Pics and Information on 2014-2022 Sportster Oil Tanks

See also in the Sportsterpedia;

..... [\\*1986-Up Oil Line Routing](#)

..... [\\*Pics and Information on stock EVO Battery Trays and Parts](#)

In 2014, the MoCo revised the oil tank again (62500017). This change coincided with a new battery tray.  
<sup>1)</sup>

It has the 10 psi pressure relief valve in the top of the tank.

If the vent line / vent tube is pinched or restricted, tank overfilled etc., excessive pressure is created in the oil tank.

The valve opens if the pressure in the tank exceeds 10 psi to prevent damage to the oil tank.

All hoses are now on the right side stacked on top of each other.

Click on any pic below to enlarge:





**Go To Technical Menu**

1)  
 Captain Johnny of the XLFORUM  
<https://www.xlforum.net/forum/sportster-motorcycle-forum/sportster-motorcycle-era-specific-and-model-specific/rubber-mount-sportster-motorcycle-talk-2004-2006/205256-oil-tank#post4647082>  
 2) 3) 4) 5)  
 photos courtesy of mototech271.com [Link to webstore](#)

From:  
<http://www.sportsterpedia.com/> - **Sportsterpedia**

Permanent link:  
<http://www.sportsterpedia.com/doku.php/techtalk:evo:oil04i>

Last update: **2024/01/05 19:10**

