SERVICE BULLETIN



M1494 2019-06-20

M1494: LATE 2019 SOFTAIL FXBB & FXLR - FRONT TIRE PRESSURE

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Revision Description			
	Initial release			
2019-06-20	Updated Vehicles Affected : Table 2			

Purpose for Service Bulletin

This bulletin informs dealers that Harley-Davidson has made a change to the front tire cold pressure on some Softail® models shipped on or after 06/17/2019. Refer to Table 2.

Vehicles Affected

Refer to Table 2.

Table 2. Softail Models and Front Tire Pressure Change

Year	Model	Cold Pressure			
Icai		From	То		
Late	FXBB	207 kPa (30 psi)	248 kPa (36 psi)		
2019	FXLR	207 KF a (30 psi)	221 kPa (32 psi)		

Markets Affected

All markets are affected.

Required Dealer Action

Since this change is compatible with earlier built 2019 FXBB and FXLR vehicles, make the following changes;

- Remove and replace any earlier printed versions of the 2019 PDI (Predelivery inspection) with the updated 2019 PDI.
- Update all 2019 Softail service manuals to reflect the change in Table 2.
- PDIs on any 2019 FXBB or FXLR should now follow this updated cold tire pressure guidance.
- The Softail owner's manual has been revised to reflect the updated recommended cold tire pressures noted in Table 2. The original 2019 Softail owner's manual (Part No. 94000536) may be used with all Softail models except FXBB and FXLR. The new 2019 Softail owner's manual (Part No. 94000764) can be used with all Softail models, and must be used with FXBB and FXLR. See Table 3 for correct owner's manual application and dealer actions required:

Table 3. Model Year 2019 Softail Owner's Manuals

Motorcycle Model	Regulatory Configuration	Correct Owner's Manual	Dealer Action Required
FXBR, FXBRS, FLFB, FLFBS, FLHC, FLHCS, FLSL, FLDE, FXFB, FXFBS, FLSB, FXDRS	All	Either 94000536 series owner's manual or 94000764 series owner's manual can be used.	No action required.
FXBB, FXLR	DOM, CAL, ENG, AUS, IND, CAN, CHN, JPN, BRZ	Models shipped on or after 6/17/2019 include the updated 94000764 series owner's manuals. Models shipped before 6/17/2019 may use the 94000536 series owner's manual.	Update printed copies of predelivery setup. Update printed copies of Softail service manuals.
FXBB, FXLR	HDI, HD4, APC, AZN	Models shipped on or after 6/17/2019 use 94000764 series owner's manual.	FXBB and FXLR models shipped on or after 6/17/2019 must be delivered with a 94000764 series owner's manual. Check all dealership inventory and replace as necessary. 94000536 series owner's manuals may continue to be used with other Softail models, and FXBB and FXLR shipped prior to 6/17/2019.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service

ROUTI	NG	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL H	IERE									