

5. Open DT II program and establish communication with vehicle.
6. Proceed to reflash BCM and follow on-screen directions.

Supplemental Procedure Video

⚠ WARNING

Always review the appropriate service procedure prior to performing it. This video is intended to supplement, not replace, documented service procedures. Attempting service procedures without the proper training, tools, equipment, and manuals could result in death or injury to you or others. This could also damage the motorcycle or cause the motorcycle to operate improperly. (10406a)

This video is a supplement of the procedure covered in the document. This video can only be viewed through Service Information Portal (SIP).



Video 1.

Credit Procedure

NOTE

Enter bulletin number into comment section of claim.

Submit a warranty claim per Table 2 for each vehicle that receives this update.

Table 2.

ITEM	DATA
Claim Type	PRD
Problem Part Number	41000678
Quantity	Leave Blank
Primary Labor Code ⁽¹⁾	6186
Time	0.2 h
Customer Concern Code	9210
Condition Code	6186
(1) Download may be required	