

January 19, 2004

Crank Position Sensor Change

We are changing our supplier for the Twin Cam crank position sensor. The new sensors have a different appearance and you will see them on production vehicles built in February 2004. You will begin to see the new sensor in P&A shipments this month. As P&A inventory is depleted all sensor part numbers will be superseded to an "A" suffix. The sensors are interchangeable so do not return or scrap the sensors in your inventory.

Current Crank Position Sensor



New Crank Position Sensor

