

December 13, 2004

Job/Time Codes

Recently there have been corrections made to two different job/time codes. Please update your manuals with the following corrections.

2002 – 2003 VRSCA models

Labor code 4517

Replace water pump/gasket/cover o-ring

Models: HAZ, HAA

New time is 2.3

2004 – 2005 FLHT, FLHR, FLTR models

Labor code 4016

Replace clutch release bearing and/or push rod

FLHT models: DDV, FVW, DJV, FFW, FKW, FCW, FLW, FGW, FMW

FLHR & FLTR models: FRW, FBW, FWW, FDV, FXV, FYW, FSW, FHW, FTW

New time is 1.2