

Tech Tip # 58 (All 2004 Items)

January 5, 2004 - FLHTCSEI Rear Speakers	2
January 12, 2004 - Softail Transmission Mounting Brackets	3
January 19, 2004 - Crank Position Sensor Change	4
January 26, 2004 - Repair Kits for Adjustable Rider Backrest Seats	5
February 2, 2004 - 1998-2002 Radio Upgrade & 2004 ECM Calibrations	6
February 09, 2004 - Accessory Instruments On 2004 Models	7
February 23, 2004 - FREIGHT CLAIM FILING PROCEDURE - VEHICLES	8
March 01, 2004 - EFI Tuner Download Issue	9
March 08, 2004 - Fuel Tank Material Change	10
March 15, 2004 - 2004 Road King Custom Bag Reflectors	11
March 22, 2004 - VRSCA/B Maxi-Fuse	12
March 29, 2004 - 2004 V-Rod Enhancements	13
April 05, 2004 - Left Rear Speaker Box	14
April 12, 2004 - Combination Speedometer/Tachometer Low Fuel Light	15
April 19, 2004 - Milliampere Draw Information	16
April 26, 2004 - Crank Position Sensors	17
May 1, 2004 - Older Tech Tips Archived	18
May 3, 2004 - Radio Sound Repair Cost Increase	19
May 10, 2004 - 2004 XL Rear Caliper	20
May 17, 2004 - Detachables Lock	21
May 24, 2004 - 5 Speed Main Drive Gear Installation - Twin Cam, XL, BUELL	22
May 31, 2004 - Labor Code Information	23
June 7, 2004 - 2004 Twin Cam Combustion Codes	24
June 15, 2004 - Screamin' Eagle Parts Information	25
June 21, 2004 - Low Fuel Lamp On EFI Models	26
June 28, 2004 - Oil Leaks?	27
July 14, 2004 - Fluctuating Fuel Gauge Readings on V-Rod	28
July 22, 2004 - 2005 Quick Facts	29
August 2, 2004 - BUELL XB models oil line clamp	30
August 05, 2004 - 2005 Performance Configurations	31
August 30, 2004 - 2005 Touring Models Maintenance Schedule	32
September 6, 2004 - Trouble Code Diagnostics	34
September 13, 2004 - Older Tech Tips Archived	35
September 20, 2004 - Halogen Headlamps	36
September 27, 2004 - Stage Calibrations	37
October 4, 2004 - Paint Repair Techniques	38
October 11, 2004 - EFI Race Tuner Calibrations	39
October 18, 2004 - Screamin' Eagle Pro Race Fueler Fitment Update	42
October 25, 2004 - Automatic VIN Detection	43
November 1, 2004 - Twin Cam Flywheels	44
November 8, 2004 - Speed Signal / Turn Signal Cancellation Issues	45
November 15, 2004 - Digital Technician News	46
November 22, 2004 - Technical Service Authorization	47
November 24, 2004 - Fuel Valve Verification Procedure	48
November 29, 2004 - Catalog Updates	50
December 6, 2004 - XL883 Ignition module calibration changes	51
December 13, 2004 - Job/Time Codes	53
December 20, 2004 - PNA Warranty Procedure	54