

March 16, 2005

**Service Bulletin M-1162**

We have been receiving warranty claims, pertaining to this bulletin, where the ICM has been replaced. This bulletin instructs you to reflash the stock ICM using Digital Technician. When you file the claim you will use the ICM part number as the problem part with the quantity of 0. Please make sure to review all Service Bulletins for the proper procedures.