

## 2006 Dyna Model Wire Harness

There is a possibility that the cable strap (1), shown in the picture below, may be applying undue pressure to the Engine Management sensor wires (2) and may cause an inferior connection. It is recommended that you remove the cable strap on any 2006 Dyna Model built on or before October 20, 2005 at PDI or at the next service. The Process for the cable strap has been changed on the assembly line to address this issue.

