

2006 Advanced Audio System Information

1. Please remember to check all radios for the latest software update (currently 7.8.0), when they come in for service. If it does not have the latest software release; please update the radio.

To view the software version installed in the radio use this procedure:

- Turn ignition ON and verify the radio is ON
 - Turn ignition OFF
 - Push and hold any 2 preset buttons
 - Turn ignition ON and wait for display to show the diagnostic screen
 - Push the Software button(preset #4) and it will display the Software version
2. The Initial Care Program has been extended until May 22, 2006. Please review Service Bulletin M-1173B for the latest information.
 3. Labor code 6114 (Replace Radio Chassis – Display Failure) has been added. This code pays an additional .1 for performing ROM Default Reset per Tech Tip 209.
 - KAV, KBW, FFW, FCW/FLW, FGW Models change to 0.7
 - FSW Models change to 0.8
 4. The amplifier uses a 30 Amp fuse and it is part number 72379-06.