

TT237 – April 4, 2006

### **Trouble Codes 35 and 44**

An issue has been found with Digital Technician software version 18.03. This software version may report false trouble codes 35 and 44 when linked to '95 – '98 fuel injected Touring models. When servicing these models, if trouble codes 35 and 44 are present on Digital Technician, observe the operation of the check engine lamp. If the check engine lamp is not reporting a trouble code, but the codes are showing on Digital Technician, ignore them. Trouble codes can also be verified on these models with Scanalyzer.