


2006 Dyna Fuse Block Labels

Some Dyna Models built prior to February 17th, 2006 could have the incorrect fuse block label installed in the electrical panel cover. Please check these bikes the next time they are being serviced for the correct label. If you find an incorrect fuse block label installed please replace it with a new label and file a warranty claim. The bottom label in the picture shows the correct label for all 2006 Dyna models. The top picture shows the incorrect label. **If the sticker needs to be replaced you can file a warranty using labor code 8888 for 0.1hrs which includes admin time.**



Note:

The P&A covers do not have a fuse block label but the same label could be added if the customer chooses to purchase one.