

TT290 – February 2, 2007

Recall 0121 Information

Under recall 0121, Service Bulletin M1179, Option #3, if the customer chooses to have the inner fairing replaced, follow these steps:

- 1) Obtain the appropriate parts order form for this recall which is attached to the Service Bulletin and can be found on h-dnet.
- 2) Write in part number 94434 on the form. This is the part number for the inner fairing.
- 3) Enter the VIN number for the vehicle.
- 4) Fax the form as instructed on the form.

NOTE: You no longer need to call Technical Service for an authorization to replace the inner fairing.