

### SE Dyna Shock Running Change

Effective Tuesday 4/29/2008 we made a change in production to the rear shocks on all CVO Dyna models. This is the list of part numbers that will need to be added to the parts book for the 2008 Screamin' Eagle Dyna.

The following list includes the service part numbers for the previous style, and new style Dyna shocks:

<b>Previous numbers</b>		<b>New numbers</b>
1561	<b>Shock Stud</b>	54666-08
54535-07A	<b>Shock</b>	54537-08
54539-07	<b>Stud Cover</b>	54516-09
6590HW	<b>Washer</b>	6113
N/A	<b>Spanner Tool</b>	HD-94700-52A

All of the original parts will continue to be sold at this time as service parts.

#### Previous Style used up to April 29, 2008



TT379 – June 12, 2008 - SE Dyna Shock Running Change

**New style used as of April 29, 2008**

