

Table of Contents

MiscRes: Video	1
Leaking / Smoking Breather Vents	1

MiscRes: Video



[Click Here](#) to reference Crankcase Ventilation in the Evo section of the Sportsterpedia.

Leaking / Smoking Breather Vents

Videos by epswing. 2005 XL1200R with stopped up breather valve units. The air cleaner was getting soaked with oil, the oil tank was smoking with the cap off, there was a cylinder base gasket leak and both breather bolts were smoking. The smoking stopped after the breather valves in the rocker boxes were replaced.

[Click Here](#) to read epswing's thread.

100-breather_bolts_smoking_before_new_breather_units_by_epswing.mp4	100-breather_bolts_not_smoking_after_new_breather_units_by_epswing.mp4
Breather Bolts Smoking Before: ¹⁾	Breather Bolts Not Smoking After: ²⁾

[Go To Technical Menu](#)

¹⁾

Link to file in Sportsterpedia:

http://www.sportsterpedia.com/lib/exe/fetch.php/video:100-breather_bolts_smoking_before_new_breather_units_by_epswing.mp4

²⁾

Link to file in Sportsterpedia:

http://www.sportsterpedia.com/lib/exe/fetch.php/video:100-breather_bolts_not_smoking_after_new_breather_units_by_epswing.mp4

From:

<https://www.sportsterpedia.com/> - **Sportsterpedia**

Permanent link:

<https://www.sportsterpedia.com/doku.php/techtalk:miscres:miscres420>

Last update: **2024/02/12 19:04**



