



# GENUINE MOTOR PARTS AND MOTOR ACCESSORIES BULLETIN



PAB1124

2022-03-04

## PAB1124: SCREAMIN' EAGLE/ÖHLINS REMOTE RESERVOIR REAR SHOCKS

### Purpose for Parts and Accessories Bulletin

To inform dealerships of select Screamin' Eagle/Öhlins Remote Reservoir Rear Shocks, Part No. 54000193 with batch number 185181, **MUST NOT** be installed on customer vehicles.

Return shock using the Defective Stock (DFS) process.

### Markets Affected

United States, Canada, Mexico.

### Summary

- The shocks were shipped without the correct amount of oil which can lead to poor performance.
- The shocks would have been delivered into dealerships in mid-to-late January 2022.
- See Figure 1. The batch and part numbers can be found on the top of the shock body.

### Questions

Contact Technical Service with any concerns regarding application. Direct all other questions to the Dealer Services Representative.




Figure 1. Product and Batch Number Location



## **Dealer Inventory**

For kits in dealer inventory, please submit a warranty claim per the table below.

Please enter the bulletin number into the comment section of the claim.

**Table 1. Parts in Dealer Stock**

<b>ITEM</b>	<b>DATA</b>
Claim Type	DFS
Problem Part Number	54000193
Quantity	Could vary
Customer Concern Code	9206
Condition Code	9106