SERVICE

BULLETIN

No. 563

November 29, 1967

HYDRAULIC FORK OIL CAPACITY-SPORTSTER / M-125

The 1968 (new design) Sportster hydraulic fork requires more oil than the 1967 and earlier fork. Fill each fork side with 4-1/2 liquid ounces after draining oil through drain plug or 5-1/2 liquid cunces when parts are assembled dry.

The 1968 M-125 Rapido hydraulic fork requires 3-3/4 liquid ounces in each fork side after being completely drained or assembled dry.

Use only hydraulic fork oil since this has the correct viscosity under all temperature conditions.

Note: Disregard Rider Handbook and Service Manual fork oil quantities for above 1968 models until such time as books are republished.