

Required Dealer Action

1. Verify motorcycle is involved in this recall and the recall is open.
2. Install Recall 0624 Exhaust Pipe Kit (Part No. 91500090). See the service manual for specific procedures.

Upon completion of the recall on any motorcycle, follow the instructions listed under the appropriate Credit Procedure. Submit recall claims promptly.

Credit Procedure: SAP System Users

For each motorcycle serviced, file an electronic recall claim using the following table:

Table 2. Non-Compliance Recall Code (0624)

ITEM	DATA
Claim Type	Recall claim
FIX ID-Found in Recall Number	C
Problem Part Number	65600149
Customer Concern Code	0624
Condition Code	9981

Upon submission of the properly completed recall claim, you will be credited the value cost of the recall kit plus 0.8 hours labor for performing the recall procedure, and the appropriate market administrative time. The recall record will be updated.

Hold all replaced parts for 60 days from date credit was issued for possible field inspection and/or request for return to factory. After 60 days, destroy and discard the parts.