SERVICE BULLETIN



M1466 2017-12-13

M1466: STREET - UPPER STEERING HEAD BEARING SEAL

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Revision Description
	Initial release
2018-10-03	Updated Section Motorcycles Affected : Table 2

Purpose for Service Bulletin

This bulletin informs dealers that Harley-Davidson has developed a new upper steering head bearing seal for fitment on Street models.

The **new** seal replaces the current seal on the upper steering head bearing only. The lower steering head bearing seal will still use the current seal. Refer to Table 3.

Current service procedures and specifications remain the same.

Motorcycles Affected

Refer to Table 2.

Table 2. Street Year and Models

Year	Model		
2015 - 2018	XG500		
2013 - 2010	XG750		
2017 - 2018	XG750A		

Markets Affected

All markets are affected.

Part Numbers

Refer to Table 3.

Table 3. Part Numbers

Current Part No.	Item Description	New Part No.
48184-01	SFAL DUST	11000188

Required Dealer Action

Update all manuals to refer to **new** seal part number.



In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service

in the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance of service.									
ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									