



Figure 4. Lower Fairing Without Gray Stripe

Motorcycles Affected

2019 Touring FLHXSE CVO.

Markets Affected

All markets are affected.

Part Numbers

Refer to Table 2.

Table 2. Part Numbers

Item	Description	Part No.
Fairing Lowers	Left, Charred Steel / Lightning Silver	57100168EJB
	Left, Black Forest / Wineberry	57100168EJC
	Right, Charred Steel / Lightning Silver	57100169EJB
	Right, Black Forest / Wineberry	57100169EJC

Required Dealer Action

U.S. Dealers: Replacement parts will be on I Serv, requiring approval by Dealer Services.

International Dealers: Contact the dealer's Technical Services Representative for approval.

There are 3 scenarios that may happen:

1. Replacement of left or right fairing lower for a later vehicle painted in the **new** paint scheme.
 - a. The order will be approved and processed.
2. Replacement of both left and right side fairing lowers for a vehicle.
 - a. The order will be approved and processed.

3. Replacement of a left or right side fairing lower for an earlier vehicle paint scheme.
 - a. Dealer Services and Technical Service will need to be engaged to ensure that both parts are replaced at the same time to ensure color match.
 - b. If the circumstances warrant, an authorization may be provided for the matching part.