SERVICE BULLETIN



M1545 2022-03-08

M1545 - 2022 FLHTK AND FLHTCUTG ALTERNATE AUXILIARY LAMPS

Purpose for Service Bulletin

This bulletin informs dealers that a certain number of 2022 FLHTK, FLHTK Shrine, and FLHTCUTG models built for Canada and DOM markets will be built with alternative auxiliary lamps.

Motorcycles Affected

2022 FLHTK, FLHTK Shrine and FLHTCUTG

Markets Affected

CAN and DOM.

Part Numbers

Refer to Table 1.

Table 1. Part Numbers

OE Part No.	Item Description	Temporary Replace- ment Part No.
68000020	AUXILIARY/FOG LAMP, LED (chrome)	68000203
68000174	AUXILIARY/FOG LAMP, LED (black)	68000239

Required Dealer Action

Table 2.

Action Required	Resolution		
NO YES	Non-Actionable: This is for informational purposes only or a technical tip.		

The interest of preserving dustomer surely and substitution, aimage should not be used in the interest of preserving substitution of substitution in the interest of th										
	ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
	INITIAL HERE									