# SERVICE BULLETIN



M1561 2022-08-19

# M1561: RECALL 0633 - DETACHABLE TOUR-PAK CONVERSION KIT

# **Reason for Revision**

Refer to Table 1.

**Table 1. Document History** 

Date	Revision Description
2022-08-19	Initial release

# **Purpose for Service Bulletin**

This bulletin informs dealers that Harley-Davidson has discovered that when Parts and Accessories (P&A) Detachable Tour-Pak Luggage Carrier Conversion Kits (Part No's. 53000916 and 53000917) are installed on 2014-2022 Touring and CVO Touring motorcycles, that these conversion kits may fail to conform to the Federal Motor Vehicle Safety Standard (No. 108; Lamps, Reflective Devices and Associated Equipment).

Specifically, if the Tour-Pak is removed and the vehicle is operated while one of these kits is installed, the green turn signal indicator will Fast Flash regardless of the functionality of the turn signal lights. As a consequence, if a turn signal light does subsequently malfunction, there is no change in flashing rate of the indicator within the instrument cluster as required by FMVSS 108 S9.3.6.

#### **Motorcycles Affected**

2014-2022 Touring and CVO Touring vehicles

#### **Markets Affected**

United States, Canada, and Mexico.

### **Part Numbers**

Parts are currently unavailable. Harley-Davidson is planning on Recall Kits (Part No. 91500111) to be available to order on October 1, 2022.

Refer to Table 2.

Table 2. Affected Detachable Tour-Pak Part Numbers

Part No.	Item Description			
53000916	Kit, Detachable Tour-Pak, black			
53000917	Kit, Detachable Tour-Pak, chrome			

#### Table 3. Kit Number

Item description	Recall Kit Part No.		
Kit, Recall, Tour-Pak Harness	91500111		

## **Required Dealer Action**

#### Table 4.

Action Required	Resolution
NO THE YES	Actionable: Any vehicle, component or software-related issues must be performed per service bulletin procedure.

- 1. Display Recall 0633 Poster to Customers.
  - Retrieve Recall 0633 poster from Service Information Portal (SIP) via ( Recall\_0633\_Poster ).
  - b. Print Recall 0633 poster.
  - Display notice poster prominently in the customer area.
- 2. Verify that all dealer inventory kits have been addressed per this Service Bulletin.
- Remove current harness from the P&A Detachable kit installed.
  - a. Remove main fuse.
  - b. Remove seat.
  - c. Remove left saddlebag.
  - d. Remove right saddlebag.
  - e. Remove cable straps securing Tour-Pak harness (Part No. 69202326).
  - f. Disconnect four wiring connectors.
  - g. Remove harness (Part No. 69202326) from vehicle's Tour-Pak.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									

- Install replacement harness from Recall Kit (Part No. 91500111) to vehicle's Tour-Pak.
  - Connect four wiring connectors for new harness to currently installed kit.
  - b. Install cable straps to secure harness.
  - c. Install right saddlebag.
  - d. Install left saddlebag.
  - e. Install seat. After installing seat, pull up on seat to verify it is secure.
  - f. Install main fuse.
- 5. Verify turn signal operation on vehicle.

# **Dealer Inventory Instructions**

- Locate all P&A Detachable Tour-Pak Luggage Conversion Kits (Part No's. 53000916 and 53000917).
- 2. Remove kits from inventory.
- Order harness Recall Kit (Part No. 91500111) for each conversion kit.
- 4. Remove Tour-Pak harness (Part No. 69202326) from kit.
- Insert replacement harness from Recall Kit (Part No. 91500111) into each kit.
- 6. Add back into inventory.

## **Credit Procedure**

Credit procedure will be updated with a Credit Table when Recall Kit (Part No. 91500111) is released for ordering. Harley-Davidson is currently planning for October 1, 2022.

2/2 M1561