

**Vehicle Cranks but Won't Start**

Since January of 2002 all P&A replacement ECM's for Delphi fuel injected models must be programmed with the proper calibration per Service Bulletin M1121A. If a calibration is not programmed into the ECM the engine will not start. A VRod ECM with no calibration will not start and will also turn on the fans for 4 seconds at key ON. The system identification data in Digital Technician will show an ECM calibration of yyyyyyyyyyyy instead of a number.