

## **Tech Tips #57**

### **Passing Lamp Changes - North American Vehicles Only**

For a short time during the 2003 model year we obtained our passing lamp sealed beam from a different supplier. The alternative sealed beam, part number 68674-69B, had a black plastic shell and exhibited a slightly different beam color. As a result, when a lamp was replaced a vehicle could have one of each lamp (68674-69A and B). Some customers objected to having two different beam colors. If the motorcycle was still within the warranty period, dealers were allowed to replace both lamps in order to obtain matching beam colors. We have now returned to the all glass passing lamp sealed beam, part number 68674-69A. If you replace a passing lamp sealed beam within warranty, we will continue our policy of covering both lamps in order to match the beam color.