

Setting Idle Speed With Digital Technician

We have had some reports of difficulty in setting the Idle RPM below 1000 rpm on 2002 and later injected FLT models and injected Softails with the latest version of Digital Technician. There are no reports of problems setting Idle RPM above 1000 rpm. Until we can investigate and correct this issue with Digital Technician please use the Scanalyzer when you want to set idles below 1000 rpm.