

March 15, 2004

2004 Road King Custom Bag Reflectors

If you have a 2004 FLHRS/I Road King Custom with a missing leather saddlebag reflector do not warranty the entire saddlebag. The reflectors are available but unfortunately were left out of our 2004 parts catalogs. The part numbers are 59288-92 for the left and 59287-92 for the right side.

Either print this page for insertion at page 174 of your 2004 Touring Parts Catalogs or write the part numbers in your catalogs. Please remember to make the changes in both your Parts and Service Departments.