

May 3, 2004

## Radio Sound Repair Cost Increase

Due to increased shipping and parts cost, Radio Sound will be increasing the repair rates for the Exchange/Repair program. The following prices will be effective June 1, 2004.

Wrecked or physically damaged items will still be quoted on an estimate basis since inspection is required to determine the extent of the damage.

Items in good physical condition will be handled in the same manner as always, just at the new price.

<u>Radios</u>	<u>Cost</u>	<u>Headsets</u>	<u>Cost</u>
76164-88	\$175.00	All P/N	\$45.00
76164-88a	\$175.00		
76164-88b	\$175.00	<u>Amps</u>	<u>Cost</u>
76164-92	\$175.00	All P/N	\$75.00
76164-92a	\$175.00		
76164-94	\$175.00	<u>Hand Mic</u>	<u>Cost</u>
76164-94a	\$135.00	All P/N	\$40.00
76164-96	\$135.00		
76164-98	\$135.00	<u>CD Changer</u>	<u>Cost</u>
76146-98	\$135.00	All P/N	\$135.00
76164-98a	\$135.00		
76146-98a	\$135.00	<u>Transceivers</u>	<u>Cost</u>
76164-03	\$135.00	MY 88-94	\$175.00
76146-03	\$135.00	MY 95-97	\$135.00
76164-04	\$135.00		
76146-04	\$135.00		
76202-04	\$135.00		

<u>Pods</u>	<u>Cost</u>
76289-89	\$175.00
77136-90	\$175.00
77136-91	\$175.00
77136-92	\$175.00
77136-93	\$175.00
77136-94	\$175.00
77136-95	\$135.00
77136-95a	\$135.00
77136-95b	\$135.00
77136-95c	\$135.00
77136-98	\$135.00