

February 28, 2005

VRSCR Front Fork Oil Level Correction

The front fork oil levels listed in the 2006 VRSCR service manual, part # 99501-06, are incorrect. Please correct your manuals with the following information.

Page 2-80:

Left side oil level should be 80 MM, 3.15 IN.

Page 2-82:

Right side oil level should be 122 MM, 4.80 IN.