

Advanced Audio System Information

1. The instructions for the kits listed below do not tell you to connect the overlay harness [6A] pin housing to the interconnect harness [6B] socket housing. The instruction sheets have been corrected and have been posted on h-dnet. The I-sheet numbers and revision dates are as follows:
 - J03640 XM Satellite Radio 08-04-2005
 - J03642 Bluetooth Hands Free Cell Phone Interface 08-04-2005
 - J03645 CB Radio Kit 08-03-2005
 - J03652 Intercom Kit 08-03-2005Please make sure you are using the latest I-sheet when installing these kits.
2. When installing a new or replacement radio you will need to calibrate the radio with Digital Technician. If this is not done the radio will beep.
3. If you install a Rear Speaker or Intercom Kit you will also need to calibrate the radio with Digital Technician before the radio will recognize these add-ons. Please be aware that the upgrade to an Intercom system is a charged reflash.
4. The 2006 FLHTCUSE model is shipped with the Amplifier in the tourpak. This will need to be installed at PDI as described in the PDI manual. The spring for the passenger headset connector is connected to the Upper Left Hand slot on the license plate holder and uses a shorter spring (p/n 76300-06). PDI Manuals may also be found on h-dnet in the Service page under Browse On-line Documents.
5. Remember to review the Initial Care Bulletin (M-1173) and be aware that Warranty Bulletin W-132 has been updated to W-132A.
6. The Electrical Diagnostic Manuals have begun to ship and should arrive at the dealership shortly.
7. To eliminate radio adjustments as a source of issues [i.e.: blank display screens or low volume complaints] it is helpful to reset the radio to its default (mid-range) settings. To reset factory defaults on the radio use this procedure:
 - Turn the ignition ON with the radio OFF
 - Push and hold buttons 1 and 3 and OK for 2 seconds
 - Push the arrow up 2 times
 - Push button 2
 - Turn off ignition for 20+ seconds
 - Turn ignition on and verify all defaults have reset
8. To view the software version installed in the radio use this procedure:
 - Turn ignition ON and verify the radio is ON
 - Turn ignition OFF
 - Push and hold any 2 preset buttons
 - Turn ignition ON and wait for display to show SOFTWARE
 - Then push the Software button and it will display the Software version
9. Further information on the Advanced Audio System can also be found on www.harley-davidson.com. Once on the web site click on Products. (on the bottom RH side of this page is also where you will find a link to information on the Road Tech Quest Navigation System) Then click on Motorcycles, scroll down to Touring and then click on Advanced Audio. This is where you find a list of cell phones that have been verified to work with the Bluetooth Hands Free Cell Phone Interface. This list will be updated when other phones are added.