

1340 V² & XL Flywheel Pinion Race Refurbishing Program Update

Beginning March 1, 2006 the following changes will be in effect for the 1340 V²/XL flywheel pinion race refurbishing program.

Part Number **23951-93AREMAN – 1987 – 1999 (3 piece) 1340 V² flywheel**

Part Number **23929-86REMAN – 1987 - * XL model flywheel**

Cost - **\$95.00**

Dealer Order Process:

- Enter a VN order electronically for the appropriate part number listed above
- System will prompt for a valid 17 digit VIN and mileage
- An order acknowledgment will be auto faxed once the order is placed
- A second fax titled “Remanufactured Part Order Received” will be auto faxed
- Enclose a copy of the second fax with the part
- Ship part freight prepaid to:

**Harley-Davidson Motor Co.
11700 W. Capitol Drive
Wauwatosa, WI 53222
Attn: Reman Dept.**

Turnaround time is 7 business days from the date the part is received at Capitol Drive. Delay in shipping the part will result in a delay receiving the part back within the program timeline.

When considering sending the right flywheel for a new pinion race, DO NOT attempt to move or remove the old race. If the pinion race has moved on the shaft during use, DO NOT SEND IT IN FOR REPLACEMENT.

This program is for 1340 V² 3 piece flywheel pinion side wheels and XL pinion side wheel only. Package pinion side flywheel securely so part doesn't get damaged during shipment. Do not ship complete flywheel assemblies. Parts that are non-repairable will be returned freight collect.