

TT239 – April 21, 2006

### **2006 Dyna Primary Chaincase Cover Drain Plug**

The torque for the 2006 Dyna primary chaincase cover drain plug is listed incorrectly in the Service Manual on page 1-26 and also in the 2006 Ready Reference book on page 25. It states to torque the drain plug to 36-60 **in-lbs** (4.1-6.8 Nm); it should read 14-21 **ft/lbs** (19.0-28.5 Nm). Please correct your 2006 Dyna Service Manuals and Ready Reference Books.