

TT256 – August 3, 2006

V-Rod Fuel Modules

Technical Service continues to field calls from dealers on the fuel module assembly (part # 75123-01B) as it requires an authorization from Technical Service to order. The reason for this is because you can order the failed part of the assembly separately and do not need to order the whole assembly.

Please refer to a 2004 & later V-Rod Parts Catalog for a break down of the parts and also review the July 14th, 2004 Tech Tip on properly diagnosing these issues (Tech Tips Archive Issue # 58).