

Buell XB Lightning & Ulysses Front Wire Harness Bracket

The front wire harness bracket, located on the left side of the steering neck, for the XB9SX, XB12S, XB12Scg, XB12Ss, and XB12X models has changed from part # C0047.1AD to Y1000.2AK. This change was implemented to prevent damage to the main wiring harness and throttle cables when the front end is turned to the full left lock position. The pictures below show the updated part.



Y1000.2AK
Front Wire Harness Cover



Y1000.2AK
Front Wire Harness Cover

There has also been a new oil fitting cover (part # Q0009.3AA) and nylon wire guard (part # M0072.02A8) added to all XB Models, it is located under the front sprocket cover. These are to prevent wires from becoming chafed or pinched. The pictures below show these items.



M0072.02A8
Wire Guard



Q0009.3AA
Oil Fitting Cover