

TT272 – October 18, 2006

2007 FX Softail Model Reflector Change

On 08/15/06 there was a running change made to the License Plate Bracket Reflector. This change involves the 2007 49 State, California and Canada configurations of FXST, FXSTB and FXSTC models. Reflector part # 59988-72A and Reflector Bracket part # 60019-93A have been removed and replaced with Reflector part # 69490-07. The new reflector is located along the top edge of plastic License Plate Bracket, centered from side to side. Please update your parts books to reflect this change.



Old Configuration



New Configuration