

Handlebar Switch Replacement Parts Change

There has been a change to some service replacement handlebar switches used on some 1996 and later models.

There was an increase in the length of the wiring that comes with the switches, this will eliminate the need to splice and solder in the switches during repairs and simplify installation of different height P&A handlebars

Obsolete part #		New Part #
71597-96B	Horn/Dimmer	71682-06
71591-00	Right Turn Signal	71683-06
71589-96B	Run/Stop/Start	71684-06
71598-00	Left Turn Signal	71685-06