

Table of Contents

MiscRes: Harley Parts and Accessories Bulletins (PAB)	1
PAB 0-199	1
PAB 200-299	4
PAB 300-399	10
PAB 400-499	16
PAB 500-599	22
PAB 600-699	26
PAB 700-799	26
PAB 800-899	26
PAB 900-999	26
PAB 1000-1099	27
PAB 1100-1199	32

MiscRes: Harley Parts and Accessories Bulletins (PAB)

See the [Misc Resource Section](#) on the Sportsterpedia main Tech Page for a list of Service Bulletins, Tech Tips etc.

- The following Parts and Accessories Bulletins were issued by Harley-Davidson to their dealer network. Some are simply price changes and such and some list parts catalog changes and parts changes and instructions. To the best of our ability, these bulletins have been displayed as issued. The Sportsterpedia is displaying these bulletins as PDFs for information only. End users are fully responsible for the results of evaluating and using this information. The Sportsterpedia makes no claims of accuracy, applicability or authentication of the information presented in these bulletins.
- Note that you can create a PDF of this page (with our listing of TSBs). CLICK on the 'export:pdf' in the menu tabs at the top of this page. Then choose to 'save' the file to a convenient location. You can then print your PDF as a booklet.
- The Table of Contents will allow you to jump into the middle of the listing.
- You can search the page using Ctrl-f. Ctrl-Home will take you to the top of the page - Ctrl-End to the end of the page.
- These files open best when using Adobe Reader. On some PDF viewer programs other than Adobe, they may not open properly.
[Click here to download the latest version of Adobe Reader.](#)
You can also find other PDF viewer programs on the net that will open them.
- When you click on one of the PDFs, Adobe Reader will load and proceed to download the chosen bulletin.
This could take some time on slow connections as some of the bulletins are larger than others.

PAB 0-199

PARTS AND ACCESSORIES BULLETINS			
P&A#	PDF?	Date	Subject
XXXX	Y	11-30-1966	1967 Parts Catalog/Supplement Changes
	Notes:	Updates 1967 parts catalogs for Electra-Glide/Duo-Glide, Sportster, Sprint and M-65 models w/ added and deleted entries.	
XXXX	Y	11-22-1974	1975 XL/XLCH Shifter Linkage Parts List
	Notes:	Parts catalog supplement page to update the parts catalog.	
XXXX	Y	11-24-1975	Engine Crankcase Policy
	Notes:	Procedure for ordering and replacement.	
XXXX	Y	1-16-1976	Sportster Rear Shock Absorbers

	Notes:	1967 thru 1974 Part #(54535-67) is replaced by part #(54547-75). And the new shock mounting conversion kit, part #(54529-76).	
XXXX	Y	4-22-1976	L1976 XL/XLCH Keihin Carburetor parts list
	Notes:	Parts catalog supplement page to update the parts catalog.	
XXXX	Y	5-18-1976	Paint Notice
	Notes:	The 1976 vivid colors except for black are air dry enamel, not lacquer which is incorrectly printed on the can labels.	
XXXX	Y	10-5-1976	Frames
	Notes:	Ordering procedure.	
XXXX	Y	10-26-1976	Spokes and Nipples
	Notes:	Metric thread spokes and nipples now used on all V-twin motorcycles.	
XXXX	Y	2-8-1977	Sportster Carb Main Jets
	Notes:	Oversized jets now available.	
P&A-21	Y	12-12-1977	Tires and Wheels
	Notes:	Tires, Tubes, Rim Strips and Wheel Asemblies.	
P&A-55	Y	11-16-1978	Air Dry Paint List
	Notes:	1957-1979 paint colors list.	
P&A-56	Y	11-16-1978	Painted Parts
	Notes:	1979 V-Twin painted parts list.	
P&A-121	Y	11-7-1980	Air Dry Paint List
	Notes:	1957-1981 paint colors and part numbers.	
P&A-122A	Y	2-10-1981	Painted Parts List
	Notes:	Painted Parts List for 1981 V-TWINS.	
P&A-154	Y	August, 1981	Non-Current Painted Parts
	Notes:	Painted Parts List for 1979 V-TWINS.	
P&A-155	Y	August, 1981	Non-Current Painted Parts
	Notes:	Painted Parts List for 1980 V-TWINS.	
P&A-172	Y	1-22-1982	Golf Cart Batteries
	Notes:	Price reduction due to a decrease in the market price of lead.	
P&A-173	Y	2-5-1982	New Sample Program
	Notes:	Dealer incentive.	
P&A-174	Y	2-1-1982	Braided Cables
	Notes:	Fitting applications.	
P&A-175	Y	3-12-1982	Product Improvements
	Notes:	New product recommendations.	
P&A-176	Y	3-12-1982	Helmet Liquidation
	Notes:	Closeouts.	
P&A-177	Y	3-12-1982	Inventory Clearance
	Notes:	Liquidation sale.	
P&A-178	Y	3-19-1982	Headlight Modulator
	Notes:	Correcting instruction sheet.	
P&A-179	Y	3-26-1982	Oil Sale

	Notes:	Pre-Luxe, Premium, and Two-Cycle oil available first-come/first-serve.	
P&A-180 P&A-180A	Y	5-5-1982	1982 FLHF/FLHS
	Notes:	Parts catalog update exclusive to 1982 FLHF and FLHS vehicles.	
P&A-181	Y	4-13-1982	FL Parts
	Notes:	Fishtail mufflers and FLCH primary belt conversion kit available.	
P&A-182	Y	5-29-1982	Changes
	Notes:	4-Pak Oil Carrier no longer free to dealers, 7" sealed Halogen headlight no longer available.	
P&A-184	Y	6-8-1982	Price List Supplement
	Notes:	To be used with May 4, 1981 price book.	
P&A-185	Y	June 1982	1983 XLX
	Notes:	Parts catalog update of parts exclusive to the 1983 XLX model.	
P&A-186	Y	7-1-1982	New 60wt Oil
	Notes:	Premium II Extra Heavy (API SF) now available.	
P&A-187	Y	8-20-1982	Price List Errors
	Notes:	In the 8-1-1982 Price List, some items were erroneously listed obsolete.	
P&A-188	Y	10-29-1982	HP Cam Gear Kit
	Notes:	This kit (80038-81) fits 1980-1981 XLS/XLH.	
P&A-189	Y	11-16-1982	Primary Drive Belts
	Notes:	A small quantity of primary drive belts (40009-80) were 'mis-packed'.	
P&A-190	Y	12-10-1982	Price Supplement
	Notes:	Comprehensive price supplement of all parts that have been priced or have changed since the August 1, 1982 Price Book.	
P&A-191	Y	1-28-1983	Aerosol Paint
	Notes:	The package quantity on all aerosol paints changed from 6 cans to 4 cans per carton effective immediately.	
P&A-192	Y	2-4-1983	New 60wt Oil
	Notes:	PREMIUM II Extra Heavy Grade 60 (API SF) now available.	
P&A-193	Y	2-11-1983	Price Supplement
	Notes:	Comprehensive price supplement of all parts and accessories that have been priced or have changed since the August 1, 1982 Price Book.	
P&A-194	Y	3-10-1983	1983 XR-1000
	Notes:	List covering part numbers exclusive to the 1983 XR-1000.	
P&A-195	Y	3-10-1983	1983 FXWG
	Notes:	List covering part numbers exclusive to the 1983 FXWG.	
P&A-196	Y	3-29-1983	Price Supplement

	Notes:	Comprehensive price supplement of all parts and accessories that have been priced or have changed since the August 1, 1982 Price Book.	
P&A-197	Y	4-19-1983	1983 FXRT
	Notes:	Instruments and indicator lamps parts listing for the 1983 FXRT model.	
P&A-198	Y	4-18-1983	Touch-up Paint
	Notes:	HD lowered the quantity on all Touch-Up Paint to two per package.	
P&A-199	Y	5-20-1983	FXR/FXRS Suspension
	Notes:	Parts for lowering 1983-earlier FXR/FXRS models up 1-1/2".	

PAB 200-299

PARTS AND ACCESSORIES BULLETINS			
P&A#	PDF?	Date	Subject
P&A-200	Y	3-15-1983	Battery (66006-65A)
	Notes:	Correcting the price in the 1983 Fashion & Accessory Catalog.	
P&A-201	Y	5-24-1983	Sissy Bar Kits
	Notes:	Kits available.	
P&A-202	Y	5-27-1983	Consumer Oil Promotion
	Notes:	The Oil-Ly Bird Special \$2.00 off coupon is in effect for the consumer through June 15, 1983.	
P&A-203	Y	6-10-1983	1983 Sellout List
	Notes:	Parts discounted.	
P&A-204	Y	7-1-1983	V-Twin Belt Buckles
	Notes:	There are a limited number of pewter Special Edition V-Twin belt buckles left over from the Recycle Days Program that are available for sale.	
P&A-205	Y	7-18-1983	1984 FXST-Softail
	Notes:	List covering most parts numbers exclusive to the 1984 FXST-Softail.	
P&A-206	Y	7-15-1983	Summer Sale
	Notes:	Correcting the 1983 Special Summer Sale booklet.	
P&A-207	Y	8-19-1983	1984 Painted Parts
	Notes:	Painted parts list for all 1984 models.	
P&A-208	Y	11-1-1983	1984 FXR - Police
	Notes:	List of parts unique to the 1984 FXR·POLICE vehicles.	
P&A-209	Y	Nov. 1983	Price Supplement
	Notes:	Comprehensive price supplement of all parts and accessories that have been priced or have changed since the August 15, 1983 Price Book.	
P&A-210		11-29-1983	Clutch Release Bearing
P&A-210A	Y	12-6-1983	Correcting to Thrust Washer

	Notes:	Update corrects verbiage. A bad shipment of Thrust Washer - Inner (37311-75A) was received by the Parts & Accessories Division and shipped to many dealers between June 15, 1983- and November 1, 1983.	
P&A-211	Y	1-20-1984	Late 1984 XL
	Notes:	Bulletin covers unique parts new parts on the L1984 improved XL models.	
P&A-212	Y	1-4-1983(4)?	FXRT Fairing Windshields
	Notes:	Three different height windshields available for the FXRT fairings.	
P&A-213	Y	1-10-1984	1979-1984 XL
	Notes:	Correcting an error in the (99451-84) parts catalog crankcase section.	
P&A-214	Y	2-17-1984	Late 1984 1340cc Parts Catalogs
	Notes:	Bulletin covers Late 1984 unique parts on 1340cc models.	
P&A-215	Y	2-17-1984	1984 FLHX
	Notes:	Bulletin covers unique parts on 1984 FLHX models.	
P&A-216	Y	2-14-1984	Levelift Centerstands
	Notes:	Price reduction.	
P&A-217	Y	2-24-1983(4?)	Returned Rider Accessories
	Notes:	New return label.	
P&A-218	Y	2-24-1984	Part Number Change
	Notes:	Changed the part number suffix letter on novelty products.	
P&A-222	Y	4-10-1984	HD (5736) Spacer
	Notes:	Price reduction.	
P&A-223	Y	4-5-1984	1979-1984 Parts Catalog
	Notes:	Late 1984 page replacement for 1979-1984 XL parts catalog (99451-84).	
P&A-224	Y	4-5-1984	1984 Parts Catalogs
	Notes:	Correcting 1984 parts catalogs due to incomplete information 1984 front forks.	
P&A-225	Y	5-18-1984	1984 Sellout list
	Notes:	Annual sellout of discontinued replacement parts.	
P&A-226	Y	6-1-1984	Connecting Rods
	Notes:	Price reduction.	
P&A-227	Y	6-12-1984	1984 FLHS-80
	Notes:	Covering unique parts on L1984 FLHS-80 Electra-Glide Sport model.	
P&A-228	Y	7-16-1984	FXRT Rider Footboard Kit
	Notes:	Parts and revised instructions for use on all FXRT models.	
P&A-229	Y	9-24-1984	1340cc Flywheel Assembly
	Notes:	New assembly includes service part (23913-85), one piece flywheel half.	
P&A-230	Y	10-9-1984	Price Supplement
	Notes:	List of all parts and accessories that have been priced or have changed since the August 1, 1984 Dealer Price List.	

P&A-231	Y	10-10-1984	Model Application Changes/Corrections
	Notes:	Correcting information in the 1984 Spring Fashions/Accessories Catalog on page 23, box K.	
P&A-232	Y	10-18-1984	1/4oz Wheel Weights
	Notes:	Clarifying that the 1/4oz wheel weight part numbers are for one (1) 3oz wheel weight strip which is segmented into twelve 1/4oz units. This bulletin was replaced by P&A-234.	
P&A-233	Y	10-18-1984	Evo 1340cc
	Notes:	Piston to valve clearance before 'hopping up' an Evo.	
P&A-234	Y	10-29-1984	Wheel Weights
	Notes:	Clarifying the 1/4oz wheel weight part numbers. Also includes Hi-Way Peg Kits to fit late '84-later XL models. This bulletin replaces P&A-232.	
P&A-235	Y	11-14-1984	Filler Cap Gasket (61109-85)
	Notes:	New gasket will fit cap assemblies 61060-82A, 61102-83A and 61103-83.	
P&A-236	Y	12-17-1984	Clutch cable Boot (38625-85)
	Notes:	This new item will fit XL clutch cables 38619-71B and 38626-77B.	
P&A-237	Y	12-17-1984	FL/FX models
	Notes:	This bulletin covers unique parts on the chrome drivetrain models.	
P&A-238?	Y	No Date	Oil
	Notes:	Changes to the oil distribution program.	
P&A-239	Y	3-8-1985	RLE Sidecar
	Notes:	This bulletin covers the parts for the RLE Sidecar.	
P&A-240	Y	2-18-1985	1985 Spring Accessories Catalog
	Notes:	Pricing items in 1985 Spring Motorcycle Fashions and Accessories Catalog.	
P&A-241	Y	2-28-1985	1340cc Rocker Arms
	Notes:	This bulletin issued to clarify the actual usage of the 1340cc Evolution V ² ROCKER ARMS.	
P&A-242	Y	3-6-1985	Leather Jackets
	Notes:	Beginning March 15, we will be offering our Cycle Champ and Cycle Queen leather jackets, all sizes, on a year-round quantity discount program.	
P&A-243	Y	3-20-1985	Screw-Speedo Reset Knob
	Notes:	New part number (67117-85) along with models it fits.	
P&A-244	Y	3-25-1985	1985 Spring Accessories Catalog
	Notes:	Delayed products and their expected availability dates.	
P&A-245	Y	4-12-1985	Oil Program
	Notes:	2nd free freight oil program and price list.	
P&A-246	Y	4-4-1985	Tool Kit
	Notes:	The Deluxe Tool Kit (94405-78) has been obsoleted. Instead, the tool pouch and tools in the kit are sold separately.	

P&A-247	Y	5-10-1985	V ² Evo Lifters
	Notes:	The v2 Evo engine has a new style valve tappet. Do not attempt to use the SE Solid Lifter Kit with these new tappet assemblies.	
P&A-248	Y	5-24-1985	1985 Sellout List
	Notes:	Annual sellout of discontinued replacement parts.	
P&A-249	Y	5-24-1985	Radio Business
	Notes:	Motorola Inc., has informed us that they are no longer in the business of manufacturing radios.	
P&A-250	Y	6-4-1985	Oil
	Notes:	We have reduced the minimum order quantity to 10 cases or 1 drum.	
P&A-251	Y	6-10-1985	Chain and Cable Lube
	Notes:	Brochure and technical information sheet on Lubit-8 chain and cable lube recently introduced by Eagle Iron.	
P&A-252	Y	6-28-1985	Inner Valve Spring
	Notes:	A certain quantity of inner valve springs (18202-83) that do not meet specifications may have been received by the Parts and Accessories Division and shipped to the dealer network.	
P&A-253	Y	7-19-1985	Spark Plugs
	Notes:	You can now order mixed quantities of spark plugs.	
P&A-254	Y	7-25-1985	Rider Accessories
	Notes:	List of discontinued or soon obsoleted products.	
P&A-255	Y	8-2-1985	Price Supplement
	Notes:	List of all parts and accessories that have been priced or have changed since the June 3, 1985 Confidential or retail price list.	
P&A-256	Y	8-1-1985	Air Dry Paints
	Notes:	List of new air dry paints.	
P&A-257	Y	8-13-1985	Candy Pearl
	Notes:	This paint is now available in quarts only.	
P&A-258	Y	9-6-1985	Turbocharger Kit
	Notes:	Due to continuing contractual problems with our supplier, HD will not make available the 91846-85 Turbocharger Kit.	
P&A-259	Y	9-6-1985	SE Carb and A/C
	Notes:	Some of the elements used in the SE carb and air cleaner kit (91731-85) may be defective. A list of common service parts is attached.	
P&A-260	Y	9-6-1985	Battery Pad (66206-86)
	Notes:	New replacement part.	
P&A-261	Y	9-6-1985	Display Rack for Leathers
	Notes:	A 4-arm rack with slant-arms (42341) is now available.	
P&A-262	Y	9-6-1985	Display Rack for Leathers
	Notes:	A 4-arm rack with slant-arms (42341) is now available.	
P&A-263	Y	10-18-1985	Headlamp Retaining Ring

	Notes:	New retaining ring (67746-85) will fit all FLT's and FLT Classic's, 1980 to present.	
P&A-264	Y	10-15-1985	Holiday Gift Ideas
	Notes:	24K gold plated and silver plated razors, silver and brass credit card cases and a solid brass double mirror case, all having an embossed bar & shield.	
P&A-265	Y	10-29-1985	Price Changes
	Notes:	Prices on some items changed effective Monday, November 4, 1985.	
P&A-266	Y	11-8-1985	Price Corrections
	Notes:	Because of a computer error, a number of novelty items in the recent October 7, 1985 Price Book and the Catalog Price List show incorrect net and retail prices.	
P&A-267	Y	12-11-1985	Rider Accessories
	Notes:	Some rider accessories have been discontinued and are no longer available.	
P&A-268	Y	12-13-1985	1982-Later XL Vertical Oil Coolers
	Notes:	Vertical mount oil cooler kits have been changed to make installation easier on 1986 models.	
P&A-269	Y	12-11-1985	Acorn Nut and Stud Kit
	Notes:	The Instruction Sheet for the Acorn Nut and Stud Kit (91734-85) omitted some steps that pertain to use on FLT/FLHT and FXR series motorcycles.	
P&A-270	Y	12-13-1985	XR-1000 Cams
	Notes:	Individual replacement cam gears are now available for the SE XR-1000 Cam Gear Kit (25480-83R).	
P&A-271	Y	12-13-1985	BD44/40 Carburetor
	Notes:	Settings and jetting information.	
P&A-272	Y	1-24-1986	Oil
	Notes:	Free freight, oil offer.	
P&A-274	Y	1-17-1986	Liberty Jacket
	Notes:	The official licensed liberty jacket, has been discontinued.	
P&A-275	Y	1-28-1986	Leather Jackets
	Notes:	Quantity jacket offer.	
P&A-276	Y	2-21-1986	1986 FLST Heritage Softail
	Notes:	Covering the unique parts on the 1986 FLST Heritage Softail. See P&A-296 for updates to this bulletin.	
P&A-277	Y	2-14-1986	Sample Program
	Notes:	Sample program details.	
P&A-278	Y	2-18-1986	Sportster Valve Guides
	Notes:	A quantity of replacement oversize Sportster valve guides may be cracked.	
P&A-279	Y	2-18-1986	New Product Spec Sheets
	Notes:	Coding the dealer net price in the spec sheets.	

P&A-280	Y	2-25-1986	Starter Brush Kit
	Notes:	This set of brushes is for the 31533-81 starter.	
P&A-281	Y	3-18-1986	Sportster Rocker Arms
	Notes:	Price reduction for 1957 TO 1985 Sportsters.	
P&A-282	Y	3-18-1986	Parts Book Corrections
	Notes:	The 1986 parts catalogs incorrectly list part (43041-85) as a spoke and nipple. The (43014-85) part is a nipple only.	
P&A-283	Y	4-7-1986	Driving Lights (68801-86)
	Notes:	Install kit with driving lights positioned above front engine guard.	
P&A-284	Y	4-11-1986	Paint
	Notes:	Effective April 15, 1986, paints eligible to qualify for free freight.	
P&A-285	Y	4-11-1986	Air Dry Paints
	Notes:	New air dry paints available.	
P&A-286	Y	4-11-1986	Gasket Sets
	Notes:	New XL883/1100 gasket sets.	
P&A-287	Y	4-15-1986	Mid 1986 Special Additions
	Notes:	Unique parts on (1986 1/2) FXRC, FLHTC and FLTC special editions.	
P&A-288	Y	4-25-1986	Brake Discs
	Notes:	Price decrease in all cases, except one.	
P&A-289	Y	5-2-1986	Radio/CB Repair
	Notes:	Recommendation for the repair of Motorola radios and CBs that are out of warranty.	
P&A-290	Y	5-2-1986	Air Filter Elements
	Notes:	Price reductions.	
P&A-291	Y	5-13-1986	Replacement Batteries
	Notes:	Dealer net pricing change.	
P&A-292	Y	6-5-1986	Engine/Crankcase and Frame
	Notes:	Policy change for ordering.	
P&A-293	Y	5-20-1986	Air Dry Paints
	Notes:	New air dry paints available.	
P&A-294	Y	6-2-1986	XL Shocks
	Notes:	Price decrease.	
P&A-295	Y	6-2-1986	Price Changes
	Notes:	Updating prices.	
P&A-296	Y	6-13-1986	1986 FLST Heritage Softail
	Notes:	Correcting fork information in P&A-276.	
P&A-297	Y	6-24-1986	Battery Acid
	Notes:	Product can't be shipped by UPS so it's be obsoleted.	
P&A-298	Y	6-24-1986	Kerker Exhaust Kit (65211-86)
	Notes:	Procedure to aid in the removal of the muffler baffle for servicing packing material.	

P&A-299	Y	7-8-1986	Sportster Gaskets
P&A-300	Y	7-15-1986	
	Notes:	New top end and complete gasket sets to simplify replacement parts.	

PAB 300-399

PARTS AND ACCESSORIES BULLETINS			
P&A#	PDF?	Date	Subject
P&A-301	Y	7-22-1986	Watches
	Notes:	Dealer net reduced.	
P&A-302	Y	7-22-1986	Price Changes
	Notes:	New price adjustments.	
P&A-303	Y	7-25-1986	Oil
	Notes:	Gallon containers delayed.	
P&A-304	Y	7-25-1986	Quantity Changes
	Notes:	Packaging and pricing changes.	
P&A-305	Y	8-15-1986	No Lead Valve Seat Inserts
	Notes:	New inserts for 1200c/1340cc 1966-up to eliminate/reduce "pitting" that occurs when using unleaded fuel. This bulletin replaced with P&A-311.	
P&A-306	Y	8-7-1986	Color Match Riding Jackets
	Notes:	Effective immediately, these jackets have been discontinued.	
P&A-307	Y	8-7-1986	SE Cam Specs
	Notes:	Screamin'Eagle high performance cam specifications.	
P&A-308	Y	8-7-1986	SE Cam and Spring Set
	Notes:	This bulletin covers a potential fitment problem on High-Performance Evolution XL Cam & Spring Kits shipped to dealers during March, 1986 through mid-June, 1986.	
P&A-309	Y	8-19-1986	Air Dry Paint
	Notes:	New air dry paints available.	
P&A-310	Y	8-19-1986	Conventional Battery (66006-65A)
	Notes:	Discontinuing sales as soon as our current supplies are exhausted.	
P&A-311	Y	8-26-1986	No Lead Valve Seat Inserts
	Notes:	New inserts for 1200c/1340cc 1966-up to eliminate/reduce "pitting" that occurs when using unleaded fuel.	
P&A-312	Y	9-12-1986	Chrome Acorn Nut and Stud Kit
	Notes:	The instructions in this kit (91734-85) have been revised.	
P&A-313	Y	8-29-1986	Footpegs (49102-86T)
	Notes:	We now have replacement U clamps available.	
P&A-314	Y	9-5-1986	FX/XL Kickstart Battery

	Notes:	Package quantity has been reduced from 5 to 1.	
P&A-315	Y	9-12-1986	Eagle Iron Battery Warranty
	Notes:	Policy update.	
P&A-316	Y	9-19-1986	Timer Screw (3570)
	Notes:	Due to a substantial cost increase from our supplier, we will no longer offer it in the Genuine line.	
P&A-317	Y	10-8-1986	Evo FXR Exhaust
	Notes:	In order for the FXR High Performance Exhaust System by Kerker (65212-86) to be installed on 1987 FXR, FXRS, FXRS-SP, and FXLR models, an additional rear bracket kit is necessary.	
P&A-318	Y	10-10-1986	Refused COD Shipments
	Notes:	Policy.	
P&A-319	Y	10-22-1986	FLST Passing Lamp (68249-86)
	Notes:	Free reinforcement kit (93529) improves load spreading on mounting brackets.	
P&A-320	Y	11-24-22-1986	Mirror Kit (91875-70B)
	Notes:	Shipments to begin after delay.	
P&A-321	Y	11-24-1986	Windshield Kit (58020-49B)
	Notes:	Lexan® windshield kit, 15" high, fits all FLH with fairing all FLHT prior to the '86 model.	
P&A-322	Y	12-5-1986	Drain Plug Washer (6286)
	Notes:	Now offered as a separate serviced part.	
P&A-323	Y	12-12-1986	Oil Filter Mounting Bracket Assembly (26353-87)
	Notes:	To simplify inventories at both the factory and the dealer level, this part will not be offered.	
P&A-324	Y	12-16-1986	1987 1/2 FXRC
	Notes:	Covering unique parts on the mid-year (1987-1/2) FXRC model.	
P&A-325	Y	1-9-1987	Transmission/Primary Lube
	Notes:	Announcing two additional shipping locations.	
P&A-326	Y	1-9-1987	Chain Tensioner Assembly (39975-86)
	Notes:	To simplify inventories at both the factory and dealer, this part will no longer be offered.	
P&A-327	Y	1-16-1987	Price Changes
	Notes:	P&A price adjustments.	
P&A-328	Y	1-31-1987	1987-1/2 FLHS
	Notes:	Covering the unique parts on the mid-year (1987-1/2) FLHS model.	
P&A-329	Y	2-6-1987	Cast Wheel
P&A-330	Y	2-6-1987	Assembly (43299-86)
	Notes:	Due to a change in vendor, the rear black 16" spoke cast wheel assembly for 1986 FLHTC/FLTC/FLHT/FLHTP models will be replaced by part number (43299-87), rear 10" spoke cast wheel assembly.	

P&A-331	Y	2-13-1987	Idler Gear Shaft (25787-57)
	Notes:	Due to declining sales and to simplify inventories at both the dealer and factory level, this part for 1957-E1984 Sportsters will no longer be offered.	
P&A-332	Y	2-20-1987	Mid 1987 FLST Special Edition
	Notes:	Covering unique parts on the mid-year (1987-1/2) FLST Special Edition.	
P&A-333	Y	2-18-1987	SE Carb and A/C Kit (91731-85)
	Notes:	This bulletin covers air filter mounting tips, adjustment tips and jetting recommendations.	
P&A-334	Y	3-3-1987	Cast Wheel Weights
	Notes:	Due to circumstances beyond our control, the following stick-on cast wheel weights are no longer available.	
P&A-335	Y	3-3-1987	Low Maintenance Batteries
	Notes:	These new batteries contain a special chemical formula that drastically reduces sulfate crystal build-up on the battery plates.	
P&A-336	Y	3-24-1987	Rear Brake M/C
	Notes:	This bulletin addresses interference with high performance exhaust systems by Kerker.	
P&A-337	Y	3-3-1987	Mid 1987 FLTC/FLHTC Special Editions
	Notes:	Covering unique parts on 1987-1/2 FLTC/FLHTC Special Editions.	
P&A-338	Y	3-6-1987	1984-87 FLT/FLHT Forks
	Notes:	To simplify inventories at both the dealer and the factory levels, fork assemblies (45430-84 & 45459-86) will no longer be offered.	
P&A-339	Y	3-31-1987	Connecting Rod Set (24281-74A)
	Notes:	These were not designed for and may fail if installed in pre-1974 BTs.	
P&A-340	Y	3-26-1987	1987-1/2 XL883 "Hugger"
	Notes:	Covering unique parts on the mid-year (1987-1/2) XL "Hugger" model.	
P&A-341	Y	4-13-1987	FXST Exhaust
	Notes:	Fitment clarification for FXST exhaust system (65213-86) by Kerker.	
P&A-342	Y	4-3-1987	FLST Headlight Assembly (67825-86)
	Notes:	List of components to fit 1986-1/2-Later FLST vehicles.	
P&A-343	Y	4-3-1987	Hex Cap Screw (3771)
	Notes:	This part is replaced by part number (41465-86) sprocket fastener kit. This bulletin replaced P&A-346.	
P&A-344	Y	4-28-1987	Sport Windshield
	Notes:	This Sport Windshield Kit (58024-87) was sampled in October 1986 and included a new product spec sheet with incorrect fitment applications.	
P&A-345	Y	4-7-1987	Sadlebag Guard Kit (90839-83)
	Notes:	Price reduced.	
P&A-346	Y	4-14-1987	Sprocket Fasteners-Cast Wheels
	Notes:	This bulletin replaces P&A-343 and corrects the torque value.	

P&A-347	Y	4-16-1987	Wrist Watches
	Notes:	Because of a chronic supply problem, we have decided to obsolete the HD wrist watches (Men's P/N #99350-BSV and Women's P/N #99351-BSV)	
P&A-348	Y	5-1-1987	XLH 1100 Anniversary
	Notes:	Covering unique parts on the mid-year 30th Anniversary Edition XLH 1100.	
P&A-350	Y	7-14-1987	XL Shifter Cam (34012-75B)
	Notes:	This shifter cam will interfere with the crankcases when installed in 1975 or 1976 XL transmissions.	
P&A-351	Y	7-10-1987	Mid 1987 FXST Special Edition
	Notes:	Covering unique parts on the mid-year (1987-1/2) FXST Special Edition.	
P&A-352	Y	7-21-1987	Sprocket Mounting Bolt (3771)
	Notes:	This sprocket mounting bolt is once again available. This bolt can be used on any chain drive vehicle with cast wheels and is mandatory on all Sportsters (1979-present) with cast wheels.	
P&A-353	Y	7-21-1987	ALLSOP Cassette Deck
	Notes:	Cassette cleaning system.	
P&A-354	Y	8-13-1987	Intercom/CB
	Notes:	New 1988 Premium Radios include an improved amplifier which is less sensitive to voltage changes.	
P&A-355	Y	8-25-1987	Speedo Mounting Bracket
	Notes:	This bracket (67080-87) was omitted from the 1987 1340 Parts catalog.	
P&A-356	Y	8-24-1987	Eagle Iron Starter
	Notes:	Due to a procurement problem with our supplier, the Eagle Iron Starter Drive Unit (31443-65TA) has been obsoleted.	
PAB-357	Y	9-25-1987	1987-1988 Fashions and Collectables Catalog
	Notes:	Corrections.	
PAB-358	Y	10-2-1987	Prive Books
	Notes:	Corrections.	
PAB-359	Y	9-30-1987	Throttle Screw Kit (56397-74C)
	Notes:	Package quantity changed from 5 to 1.	
PAB-360	Y	10-21-1987	1988 SE 1340cc Camshafts
	Notes:	As a running change in 1988 Evolution 1340cc models incorporates new camshaft machining dimensions which has eliminated the need to use cam gear spacing washers.	
PAB-361	Y	10-6-1987	CB Kit
	Notes:	Installation on 1988 FL TC/FLHTC models.	
PAB-362	Y	11-6-1987	Filler Cap/Insert Assemblies
	Notes:	New parts.	
PAB-363	Y	10-30-1987	XL Buckhorn Handlebar Conversion
	Notes:	List of switch assemblies long enough to accommodate buckhorn handlebars.	

PAB-364	Y	11-3-1987	Sidecar Bodies
	Notes:	Four new part numbers, based on color structure for sidecar bodies.	
PAB-365	Y	11-12-1987	Oil Pump Drive Gear 25T (26345-39)
	Notes:	Due to a substantial cost increase, we will no Longer offer this part.	
PAB-366	Y	11-12-1987	Insulated Thermos and Chopper Glass Sculpture
	Notes:	Ordering procedure.	
PAB-367	Y	11-17-1987	Clutch Friction Disc (37931-84A)
	Notes:	Due to a procurement problem with our supplier, this part has been obsoleted and superseded to (37931-84).	
PAB-368	Y	12-18-1987	Oil Control Cylinders and Piston Assemblies
	Notes:	In the interest of consolidating inventory at the dealer and factory levels, we have obsoleted kits 16508-81 and 16509-81.	
PAB-369	Y	1-2-1988	Brake Pad Set (44135-74)
	Notes:	This pad set contains sintered bronze (metallic) pads that must not be installed on 1972- 1975 FUFX models equipped with the original hard chrome plated brake discs.	
PAB-370	Y	2-23-1988	Sportster SE Performance Parts
	Notes:	Two new Screamin' Eagle parts will soon be available to assist you in obtaining optimum performance from Evolution XL models.	
PAB-371	Y	2-19-1988	Battery Exhaust Tube (65995-88)
	Notes:	New clear high quality PVC tubing for certain 12 volt batteries.	
PAB-372	Y	2-26-1988	Breather Valve Kit (25313-73)
	Notes:	This kit for all 1200cc engines, 1941-early 1977, will no longer be offered. All components must be purchased individually.	
PAB-373	Y	5-1-1988	Reman. head Assemblies
	Notes:	Price changes.	
PAB-374	Y	5-15-1988	Mid 1988 FLTC/FLHTC/FXRS 85th Anniversary Editions
	Notes:	Covering un1que parts on the mid-year 85th Anniversary models.	
PAB-376	Y	5-22-1988	1988 FLHS Tour-Pak
	Notes:	New parts.	
PAB-377	Y	5-20-1988	Dunlop Tires
	Notes:	Dunlop tires are now available in all sizes that are currently being used on original equipment.	
PAB-378	Y	4-26-1988	Mid 1988 FXTS Anniversary Edition
	Notes:	Covering unique parts on mid year FXSTS Anniversary Edition.	
PAB-379	Y	4-12-1988	Birch White Aerosol Paint
	Notes:	Pricing and package quantity changes.	
PAB-380	Y	4-29-1988	Front Fender Brackets
	Notes:	This fender, introduced in the 1988 Eagle Iron Parts and Accessories Catalog, has been temporarily obsoleted due to unacceptable quality.	

PAB-381	Y	5-13-1988	S100® Cycle Wash
	Notes:	Promotion.	
PAB-382	Y	5-17-1988	XL Combustion Chamber Kit (25629-88)
	Notes:	It has come to our attention that instruction sheets for this kit were not included in our initial packaging prior to dealer introduction in April of this year.	
PAB-383	Y	5-27-1988	Springer Parts
	Notes:	Price Lists.	
PAB-384	Y	6-7-1988	XL Chrome Cam Cover w/Cams (25483-87)
	Notes:	This kit will fit 1986-1987 XLs only due to pinion gear change in '88.	
PAB-385	Y	6-21-1988	Dunlop Tires
	Notes:	Reminder for ordering.	
PAB-386	Y	6-28-1988	Removable Tattoo Kit
	Notes:	Harley-Davidson's removable tattoo kit has been obsoleted.	
PAB-387	Y	7-21-1988	XL883 Horn Kit (69014-88)
	Notes:	The instruction sheet supplied with this kit is incorrect.	
PAB-388	Y	7-22-1988	Price Changes
	Notes:	Price updates.	
PAB-389	Y	7-28-1988	Racing Information
	Notes:	Some piston and ring assemblies have been obsoleted.	
PAB-390	Y	8-5-1988	XL1200 SE Piston Kit (16140-87)
	Notes:	An XL-1200 SE piston kit erroneously contained 1340 Evo pistons.	
PAB-391	Y	8-8-1988	Springer Front End Kit (46007-88)
	Notes:	Price increase.	
PAB-392	Y	8-31-1988	Ultra Classic Fairing Lowers
	Notes:	Some part numbers were inadvertently omitted from the 1989 Painted Parts List.	
PAB-393	Y	9-13-1988	Crankpin Kit (23964-84RB)
	Notes:	This part #, standard size, is no longer sold. Components now sold separately.	
PAB-394	Y	9-30-1988	DECO Spots and Letters Kit (93020-88)
	Notes:	Guidelines for using this kit.	
PAB-395	Y	9-30-1988	Stripe and Frame Touchup Paints
	Notes:	List of Air Dry Lacquer Stripe and Frame touch-up paints for 1985-1989 stock production vehicles.	
PAB-396	Y	10-7-1988	Cruise Control
	Notes:	Price Changes.	
PAB-397	Y	10-25-1988	Jacket and Vest Sizing
	Notes:	Size Chart	
PAB-398	Y	11-11-1988	Low Restriction Oil Filter (63806-83)

	Notes:	This part now obsolete.	
PAB-399	Y	11-4-1988	1989 Ultra Sidecar
	Notes:	Covering unique parts on the 1989 TLE-Ultra Sidecar.	

PAB 400-499

PARTS AND ACCESSORIES BULLETINS			
PAB#	PDF?	Date	Subject
PAB-400	Y	10-28-1988	KING Tour-Pak Lamp Kit (68012-88)
	Notes:	The lamp housing in this kit can be color matched to customers tour-pak.	
PAB-401	Y	1-6-1989	1989 FLHS Painted Side Covers
	Notes:	Correcting the 1989 Painted Parts List.	
PAB-402	Y	12-6-1988	Ultra Classic Sidecar
	Notes:	Price list.	
PAB-403	Y	12-1-1988	Oil and Specialty Lubes
	Notes:	Price increase.	
PAB-404	Y	12-9-1988	XL Custom Painted Peanut Tank
	Notes:	Procedures for ordering.	
PAB-405	Y	12-13-1988	Denim Jackets and Jeans
	Notes:	Ordering Procedure.	
PAB-406	Y	12-20-1988	Oil and Specialty Lube
	Notes:	Price increase.	
PAB-407 P&A-407A	Y	2-24-1989	1987-1989 BT Parts catalog
	Notes:	Updating omitted parts.	
PAB-408	Y	1-16-1989	Springer Front End Kit (46007-88)
	Notes:	No Springer front end kits were shipped with a Jiffy Stand, as it is not required.	
PAB-410	Y	1-27-1989	Mid 1989 FXRS-CON
	Notes:	Covering unique parts for the mid-year (1989-1/2) FXRS-CON model.	
PAB-411	Y	1-27-1989	1989 Vivid Black FLTC/FLHTC ULTRA
	Notes:	Covering unique painted parts on Vivid Black FLHTC-Ultra & FLTC-Ultra.	
PAB-412	Y	2-28-1989	Tires
	Notes:	Price corrections.	
PAB-413	Y	3-2-1989	Reman. Head Assemblies

		Notes:	Price increases due to increased costs in manufacturing and less than expected return of cores.
PAB-414	Y		3-20-1989 Microfiche Viewers
		Notes:	Due to a price increase received from the vendor, it is necessary for us to increase the prices on Eyecom Microfiche Viewers and related options/accessories.
PAB-415	Y		3-22-1989 Stereo Helmet Headsets
		Notes:	Model fitment.
PAB-416	Y		3-31-1989 Sample Program
		Notes:	Policy.
PAB-417	Y		3-28-1989 Denim Flattop Hat
		Notes:	Delay in availability.
PAB-418	Y		4-4-1989 Price Book
		Notes:	Corrections.
PAB-419	Y		4-4-1989 Sterling Silver Rings
		Notes:	Correcting specs.
PAB-422	Y		4-18-1989 Tattoos
		Notes:	Price corrections.
PAB-423	Y		5-15-1989 Reman. Head
		Notes:	Policy.
PAB-424	Y		5-26-1989 Parts Available
		Notes:	Valve seat inserts and guide.
PAB-425	Y		5-23-1989 Designer Store Interior Signage
		Notes:	Correcting the spec. sheet.
PAB-426	Y		6-27-1989 SE High Flow Carb and A/C Kit (91731-88)
		Notes:	Installation clarification.
PAB-427	Y		7-27-1989 Master Cylinder Rebuild kit (42374-82A)
		Notes:	This kit is no longer available.
PAB-428	Y		8-1-1989 Racing Parts
		Notes:	Price changes.
PAB-429	Y		8-3-1989 "1903 Wheel" Lighter
		Notes:	Correcting price listing.
PAB-431	Y		9-5-1989 Sportster Saddlebag/ Sissy Bar Plate
		Notes:	The proper fitment for XL Side Plate Kit (52782-82A) and Saddlebag Support Kit (90799-86) is 1982-1989 XL models. See also P&A-441.
PAB-432	Y		9-11-1989 Chrome Lower Belt Guard
		Notes:	Included instruction sheet that covers installation on FX Softail.

PAB-434	Y	10-9-1989	1990 Painted Parts
	Notes:	Price list.	
PAB-435	Y	9-29-1989	1990 FLSTC
	Notes:	Popular accessories that don't fit this model.	
PAB-436	Y	9-29-1989	1990 FXRT Tour-Pak
	Notes:	Pinstripe changes.	
PAB-437	Y	10-9-1989	1990 Fairing and Lower Caps
	Notes:	Addition to painted parts list.	
PAB-438	Y	10-17-1989	Catalog Price Correction
	Notes:	Price error in Fall/Winter 1989 Motor Clothes and Collectibles Catalog.	
PAB-439	Y	11-14-1989	Price Reductions
	Notes:	Prices reduced on a few parts.	
PAB-440	Y	12-22-1989	1990 BT Clutch
	Notes:	Applications for both cork and paper friction plates.	
PAB-441	Y	12-8-1989	Sportster Saddlebag/ Sissy Bar Plate
	Notes:	Follow-up from P&A-431 regarding fitment.	
PAB-442	Y	1-5-1990	Price Change
	Notes:	Updating prices.	
PAB-444	Y	2-23-1990	Painted Parts
	Notes:	Update to the 1990 painted parts list for FLTC/FLHTC.	
PAB-445	Y	3-2-1990	Cruise Control Kit
	Notes:	Changes for parts in the kit.	
PAB-446	Y	3-2-1990	Convertible Saddlebag Hardware & Rivet Kit
	Notes:	New repair kit.	
PAB-447	Y	3-2-1990	Rocker Box Gasket Kit
	Notes:	Two new gasket kits available for XL and Big Twin models.	
P-13	Y	3-16-1990	XLH Belt Drive Kits
	Notes:	Some 126 tooth belts (40022-91) on XLH belt kits were manufactured incorrectly with wrong cord material and will move on both sprockets toward wheel and crankcase.	
PAB-448	Y	No Date	Microfiche Viewing Equipment and Options
	Notes:	Available equipment.	
PAB-449	Y	4-17-1990	Catalog Price Corrections
	Notes:	Corrections to the Spring 1990 Accessories Catalog.	
PAB-451	Y	5-8-1990	Semi-Synth Transmission Fluid
	Notes:	You may have been shipped some quantity of contaminated transmission lubricant in late February or early March of this year.	
PAB-452	Y	5-8-1990	Cycle King Jacket

	Notes:	Now available in long sizes.	
PAB-454	Y	6-12-1990	Chrome Hardware
	Notes:	New chrome hardware to the Eagle Iron parts and Accessories line.	
PAB-455	Y	7-6-1990	Collectables
	Notes:	The Motor Clothes and Collectibles department will send two (2) Specification Sheets with every new product.	
PAB-456	Y	8-27-1990	Cycle King Jackets
	Notes:	Size changes.	
PAB-458	Y	8-27-1990	Rod Assembly/Oil Slinger
	Notes:	The part has been obsoleted until such time it is used in 1991 production.	
PAB-459	Y	8-14-1990	Oil
	Notes:	Price increase.	
PAB-460 P&A-460A	Y	8-17-1990	Confidential Price List
	Notes:	New products.	
PAB-461	Y	8-22-1990	Battery (65989-90A)
	Notes:	Correcting shipping labels.	
PAB-462	Y	9-6-1990	Fat Boy Seat
	Notes:	Part number (52504-89) has been discontinued and replaced by the Solo Saddle and Pillion Seat sold as separate pieces.	
PAB-463	Y	9-10-1990	Rocker Box Gaskets
	Notes:	The cork-rubber rocker cover gasket (17955-84) has been made available for use on Big Twin vehicles.	
PAB-464	Y	9-12-1990	1987 FLT/FXR Transmission Case
	Notes:	Transmission Case (34730-87) has been obsoleted and superceded by P/N (34730-88).	
PAB-465	Y	9-14-1990	Inition Module and Wiring Harness Kit
	Notes:	All OE and SE ignition modules will now be supplied in the 1991 wiring configuration with a seven pin type connector.	
PAB-466	Y	9-17-1990	Sidecar Connection Kit
	Notes:	Sidecar connection kit (87106-79) for 1979-1984 FLH Models, will be obsolete when the existing inventory is gone.	
PAB-467	Y	9-17-1990	XL Transmission Shifter Forks
	Notes:	There are several different length shift forks available for 1990 and earlier XL models.	
PAB-468	Y	9-17-1990	Primed Fiberglass Parts

	Notes:	Fiberglass Parts are now available to you finished in primer and drilled to accept mounting hardware.	
PAB-469	Y	9-17-1990	1986-1990 XL Camshaft and Pinion Gears
	Notes:	The new color code system will combine the single dot and double dot sizes into a new expanded range that is identified by color only.	
PAB-470	Y	9-17-1990	FXDB Fuel Tank and Fenders
	Notes:	Part numbers for the 1991 FXDB Dyna Sturgis fuel tank and fenders.	
PAB-471	Y	9-17-1990	Price List
	Notes:	Correcting prices.	
PAB-472	Y	9-18-1990	Sample Program
	Notes:	Some dealers may not have received the correct quantity of 'Gold Eagle" gas cap medallions.	
PAB-473	Y	9-24-1990	Painted Parts
	Notes:	"Painted to Match" Tour Paks are now available for 1991 FLHS models.	
PAB-474	Y	10-5-1990	Oil
	Notes:	Price increase.	
PAB-475	Y	10-19-1990	Price Correction
	Notes:	Updating price list on a few items.	
PAB-476	Y	2-7-1991	Oil
	Notes:	Price decrease.	
PAB-477	Y	3-28-1991	Dual Disc Conversion for FXDB-STURGIS
	Notes:	Parts list.	
PAB-478	Y	4-30-1991	Oil
	Notes:	Another price decrease.	
PAB-480	Y	7-30-1991	Specialy Lubes
	Notes:	Price decrease.	
PAB-481	Y	8-23-1991	Reconditioned Prime Tanks and Fenders
	Notes:	Discounted prices.	
PAB-482	Y	9-24-1991	Kid's Sweatshirts
	Notes:	Part numbers are reversed on page 27 of the MotorClothes catalog.	
PAB-483	Y	10-25-1991	Wheel Bearing Spacers
	Notes:	Wheel Bearing spacing for all 1992 models has been changed to a new spacer with shims to set the proper wheel bearing end play. Please refer to Service Bulletin M-1013.	
PAB-484	Y	10-14-1991	Price Reduction

	Notes:	Price updates on a few parts.	
PAB-485	Y	11-8-1991	Lower Gearing
	Notes:	Unique part numbers that are needed to convert domestic models to the Touring Gear Ratio.	
PAB-486	Y	11-11-1991	Rear Sprockets for 1340cc
	Notes:	New black painted sprockets.	
PAB-487	Y	11-11-1991	1340cc Oil Pump
	Notes:	New painted oil pump parts.	
PAB-488	Y	11-15-1991	Panhead Jackets
	Notes:	Reason why Panhead jacket will vary in color from very light-very dark.	
P-20	Y	11-18-1991	Brake Pad & Rotor Replacements
	Notes:	Recommended brake pad application when a new stainless steel brake rotor is installed on 1991 and earlier models.	
PAB-489	Y	1-28-1992	Quart Paint Price Increase
	Notes:	Due to VOC (Volatile Organic Compound) regulations in certain areas of the U.S., our supplier has found it necessary to change the formulation of our quart paints.	
PAB-490	Y	3-30-1992	Price Increases
	Notes:	Due to increased manufacturing costs because of very low demand, it is necessary to increase pricing for some Genuine O.E. Service Parts.	
PAB-491	Y	4-6-1992	Price Increases
	Notes:	Price changes to Spring 1992 price books.	
PAB-492	Y	4-3-1992	RK O-Ring Chain Link Kit (40031-85T)
	Notes:	Kit may have been incorrectly packaged with "rivet" type connecting links instead of "clip" type connecting links.	
PAB-493	Y	5-26-1992	Price Increase
	Notes:	Due to increased vendor and manufacturing costs, we have found it necessary to raise pricing on these Genuine O.E. service parts.	
PAB-494	Y	7-8-1992	Battery Cable
	Notes:	Part number (70064-89) is now obsolete.	
PAB-495	Y	9-18-1992	Genuine Primed Fiberglass
	Notes:	Fiberglass Parts are available to you finished in primer and drilled to accept mounting hardware.	
PAB-496	Y	9-25-1992	Rubber Boot (70654-86)

	Notes:	Part number for the boot used with 3-Way function switch (1986-present) and volume control switch on 1988-present) vehicles with a Premium Sound System.	
PAB-498	Y	2-26-1993	Price Corrections
	Notes:	Updating prices.	
PAB-499	Y	3-12-1993	Chrome Triple Saddlebag Rail Kit (90845-93)
	Notes:	Price increase.	

PAB 500-599

PARTS AND ACCESSORIES BULLETINS			
P&A#	PDF?	Date	Subject
PAB-500	Y	3-31-1993	Oil and Lube.
	Notes:	New prices.	
PAB-501	Y	4-26-1993	Handlebar Switch Plate (71557-93)
	Notes:	Identifying part number.	
PAB-502	Y	5-3-1993	Price Corrections
	Notes:	Correcting Spring 1993 Price Books and/or Accy catalog.	
PAB-503	Y	6-11-1993	Price Increase
	Notes:	We must increase our prices due to low demand and increased manufacturing costs.	
PAB-504	Y	6-30-1993	1994 1340 Rear Sprocket Changes
	Notes:	Due to a change in the primary drive ratio on 1994 1340 models, some 1994 1340 models, International and U.S., have different rear drive sprockets.	
PAB-505	Y	7-15-1993	Price Correction
	Notes:	Correcting price for Chrome Hardware Kit-Side Cover (94286-93T).	
PAB-506	Y	7-21-1993	Price Correction
	Notes:	Correcting price for Semi/Synth Transmission Lube 55 Gallon Drum.	
PAB-507	Y	9-30-1993	Fillister Head Screw (2695W)
	Notes:	Some dealers have received this part with incorrect thread pitch.	
PAB-508	Y	10-29-1993	Sportster Oil Tanks
	Notes:	Two retrofit oil tank kits for 1982-1993 Sportster models except, XR-1000, will be available in late October-early November of this year.	
PAB-509	Y	12-19-1993	Genuine Primed Fiberglass

	Notes:	Fiberglass and ABS parts available to you finished in primer and drilled to accept mounting hardware. This bulletin is an update of PAB-495, then PAB-523.	
PAB-510	Y	5-5-1994	Lower Gearing
	Notes:	Unique part numbers that are needed to convert domestic models to the Touring Gear Ratio. This bulletin is an update of PAB-485, further updated in PAB-524.	
PAB-511	Y	2-1-1994	Sportster Preformed oil Hose
	Notes:	HD has developed a new-style engine oil return hose (62352-94B) for all 1991-early 1994 XLH Sportster models.	
PAB-512	Y	2-8-1994	FLT Antenna Set Screw (3266)
	Notes:	New part.	
PAB-513	Y	3-1-1994	Deutsch Electrical Connectors
	Notes:	These are used on all 1994 XLH and FLT models. Bulletin updated in PAB-526.	
PAB-514 PAB-514A PAB-514B	Y	4-7-1994	FLHR Road King Tour-Pak/Backrest
	Notes:	Installation clarification. Bulletin updated by PAB-522.	
PAB-515	Y	3-14-1994	Price Changes
	Notes:	Updates.	
PAB-516	Y	3-14-1994	1994 P&A Catalog
	Notes:	Ordering Information.	
PAB-517	Y	3-22-1994	Cylinder Studs
	Notes:	Changes and installation to XLH and 1340cc cylinder studs.	
PAB-518	Y	3-21-1994	Hardware Trays
	Notes:	Price changes.	
PAB-519	Y	4-11-1994	Price Corrections
	Notes:	Updates to the Spring '94 price books and/or your Accessory Catalog.	
PAB-520	Y	5-2-1994	1994 Genuine Accessories Catalog
	Notes:	Corrections.	
PAB-521	Y	6-6-1994	Price Increase
	Notes:	Due to increased manufacturing costs it has become necessary to raise the following Racing Parts	
PAB-522	Y	7-25-1994	FLHR Road King Tour-Pak/Backrest
	Notes:	Installation clarification. Bulletin updates by PAB-514B.	
PAB-523	Y	7-25-1994	1980-1985 Genuine Primed Fiberglass

	Notes:	Fiberglass and ABS parts available to you finished in primer and drilled to accept mounting hardware. This bulletin is an update of PAB-509.	
PAB-524	Y	7-25-1994	Lower Gearing
	Notes:	Unique part numbers that are needed to convert domestic models to the Touring Gear Ratio. This bulletin is an update of PAB-510.	
PAB-525	Y	8-31-1994	FLSTN-Stlye Saddlebag Kits
	Notes:	New part for all 1984-1995 Softail.	
PAB-526	Y	8-15-1994	Deutsch Electrical Connectors
	Notes:	Update to PAB-513.	
PAB-527	Y	11-15-1994	Brake Pads
	Notes:	Price reduction.	
PAB-528	Y	9-15-1994	Oil
	Notes:	Price increase.	
PAB-529	Y	9-2-1994	1994 Genuine Accessories Catalog
	Notes:	Correction.	
PAB-530	Y	11-1-1994	Primed Fuel Tanks
	Notes:	Price corrections.	
PAB-531	Y	12-22-1994	1995 Spring Price Books
	Notes:	Price revisions.	
PAB-532	Y	1-23-1995	1995 Spring Price Books
	Notes:	Price revisions.	
PAB-533	Y	1-24-1995	Oil
	Notes:	Price increase.	
PAB-534	Y	2-10-1995	1995 FLHTCU-1
	Notes:	List of service parts.	
PAB-535	Y	2-10-1995	Common Hardware
	Notes:	List of common fasteners used on HD motorcycles.	
PAB-536	Y	1-31-1995	1995 Slip Fit Muffler
	Notes:	Labeling error.	
PAB-537	Y	3-10-1995	Cruise Control Modules
	Notes:	HD's inventory of modules 70958-89A and 70958-908 is depleted.	
PAB-539	Y	2-27-1995	FLHR Saddlebag Guardrails
	Notes:	A small quantity of the FLHR Saddlebag Guardrails that were recently sampled may be defective due to chrome plating fluid staining/corroding the chrome finish.	
PAB-540	Y	3-7-1995	Genuine Parts Catalog
	Notes:	Corrections.	
PAB-542	Y	4-15-1995	Lubes
	Notes:	Price increase.	
PAB-543	Y	4-25-1995	Tires
	Notes:	Price increase.	

PAB-544	Y	7-31-1995	Various Parts
	Notes:	Price increase.	
PAB-545	Y	9-1-1995	Various Parts
	Notes:	Price increase.	
PAB-546	Y	9-8-1995	1996 Essential Parts Kit
	Notes:	Shipping.	
PAB-547	Y	9-18-1995	Low Contact Ratio Transmission Gears
	Notes:	List of discontinued items.	
PAB-549	Y	11-3-1995	Cruise Control Kit (77127-93A)
	Notes:	Kit no longer available. There will now be four individual kits.	
PAB-550	Y	11-15-1995	Oil Filter Fitment
	Notes:	2 EAGLE IRON oil filters will not work on EFI vehicles due to their overall size.	
PAB-551	Y	12-18-1995	Novus Polishing Products
	Notes:	Due to the escalating prices of corrugated boxes, it has become necessary to adjust our pricing on the following Novus polishing products.	
PAB-552	Y	12-18-1995	Tires
	Notes:	Price increase.	
PAB-553	Y	1-17-1996	Profile Low Front Suspension Kit Jiffy Stand
	Notes:	Application.	
PAB-554	Y	3-4-1996	FLSTC Docking Hardware (53371-95)
	Notes:	Price increase.	
PAB-555	Y	3-13-1996	POP Information Matrix Booklet Covers
	Notes:	The rubber material near hinge joint may crack on some of the covers.	
PAB-556	Y	3-26-1996	Fuel Tank Bracket (61348-96A)
	Notes:	Price adjustment.	
PAB-557	Y	4-15-1996	FLHR Road King Detachable Rack Update
	Notes:	Long-term durability testing.	
PAB-558	Y	May 1996	Touring Mufflers
	Notes:	New style mufflers and end caps are now sold separate & are not interchangeable with old style mufflers/ end caps.	
PAB-559	Y	5-24-1996	Batteries
	Notes:	Change in packaging quantities.	
PAB-560	Y	7-1-1996	Price Books
	Notes:	Price changes.	

PAB-562	Y	6-24-1996	Lubes
	Notes:	Part number changes.	

PAB 600-699

PAB 700-799

PAB 800-899

PARTS AND ACCESSORIES BULLETINS			
P&A#	PDF?	Date	Subject
PAB P-49	Y	11-17-2000	SE Cartridges
	Notes:	Due to a worldwide shortage of microchips, HD has worked closely with SPX Corp. to develop new multiple download/calibration cartridges for ECM recalibration of Touring and Softail models	
PAB P-52	Y	12-3-2002	Sidecar Parking Brake Kit Update
	Notes:	Revised parking brake kit for Touring models built after 5-6-2002.	
PAB P-56	Y	1-14-2003	Chrome Hardware Torque Procedure for Parts (43245-00, 43253-00A AND 94773-00)
	Notes:	New torque procedure for 2000-later Softail and Dyna rear sprocket, mounting hardware and hubcap kits.	
PAB-849	Y	5-17-2005	SYN3
	Notes:	HD has updated the fitment and has extended the service intervals for SYN3 lubricant in primary chaincase and transmission applications.	

PAB 900-999

PARTS AND ACCESSORIES BULLETINS			
P&A#	PDF?	Date	Subject
PAB-912A	Y	4-25-2014	Advanced Audio System - Out of Warranty Repair Process

	Notes:	Informing dealers of the out of warranty repair process for Advanced Audio System components.	
PAB-931	Y	4-1-2008	Michelin 150/80-16 Rear Commander Tire Update
	Notes:	In some cases, this tire (43252-07) can be challenging to mount on tubeless 3.0" wide rims.	
PAB-937	Y	5-13-2008	SE Super Tuner/Digital Technician II
	Notes:	Changes to pricing for both the Super Tuner (32109-08) and the Digital Technician II (DTII) Performance download calibrations.	
PAB-950	Y	7-24-2009	MAP Sensor Part# Update
	Notes:	Part number changes and applications.	

PAB 1000-1099

PARTS AND ACCESSORIES BULLETINS			
P&A#	PDF?	Date	Subject
PAB P-68	Y	4-11-2014	Thermostat (26700001) Inventory Return
	Notes:	Notifying dealers to return early inventory of outdated thermostats.	
PAB-1001A	Y	4-25-2014	Boom! Box Audio System
	Notes:	Out of Warranty Repair Process.	
PAB-1019	Y	3-28-2014	7" Electra Glo Light Ring Wiring Issue
	Notes:	Informing dealers that some 7" Electra Glo Light Rings were shipped with wiring too short to allow proper installation on MY14 Touring models.	
PAB-1020	Y	5-14-2014	Handlebar Installation Instructions
	Notes:	Handlebar Installation Requirements V3.0 is now available on h-dnet.com.	
PAB-1021	Y	5-14-2014	4-Point Docking Hardware Kit — Rushmore Models
	Notes:	Communicating changes to the design and the availability of a new 4-Point Docking Hardware Kit for 2014-later Touring model (Part# 52300353).	
PAB-1022	Y	6-30-2014	2002-2006 V-Rod Fuel Module Component Replacement

	Notes:	Communicating the solution and timing regarding the availability of the 02-06 VRSC and 06 VRSCR fuel pump module, fuel sending unit, and fuel module flange assembly.	
PAB-1024	Y	8-11-2014	Diamondback & Diamond-Black ABS Lower Brake Line
	Notes:	Informing dealers of the revision to XL Lower ABS Brake Lines for 2014-later models due to a manifold update and what to do regarding existing inventory.	
PAB-1027	Y	8-26-2014	Road Glide Chrome Clutch Bracket, Master Cylinder Reservoir Kit Launch Delay
	Notes:	Due to a late development issue, the launch of the Road Glide Chrome Clutch Bracket and Master Cylinder Reservoir Kit is delayed until October 31, 2014.	
PAB-1030	Y	9-12-2014	Discontinuation of Accessory Tri Glide 14-Spoke Wheel - Mirror Chrome
	Notes:	The packaging label on part (43000031) has incorrect fitment.	
PAB-1031	Y	11-18-2014	Burst Front Axle Nut Cover
	Notes:	The packaging label on part (43000031) has incorrect fitment.	
PAB-1032	Y	11-21-2014	New Road Glide Accessory Handlebars Now Available
	Notes:	New Accessory Handlebars for 2015 Road Glide vehicles (except CVO models) are in stock and ready to ship.	
PAB-1035	Y	2-3-2015	Sportster Side Cover Clip Improvement
	Notes:	We have modified the parts to improve the fit between the clips.	
PAB-1036	Y	2-12-2015	Functional Issue with Illuminated Windshield Trim
	Notes:	Informing dealers of a functional issue with the initial shipments of the new Rushmore Illuminated Windshield Trim launched at January 2015 RRE.	
PAB-1037	Y	2-13-2015	Road Zeppelin Seat Product Updates
	Notes:	The purpose of this bulletin is to communicate changes to the Road Zeppelin Seats and Seat Pads.	
PAB-1038	Y	2-1-2015	Buell Engine Assemblies
	Notes:	HD has a number of Buell engine assemblies that we would like to offer for sale at a onetime special price.	

PAB-1040	Y	3-3-2015	New SE Performance Products Launched at 2015 Retail Readiness Event — Product Information Updates
	Notes:	Some Boom! Audio Amplifiers are not currently able to be programmed.	
PAB-1041	Y	3-4-2015	Boom! Audio Amplifier Software Issue
	Notes:	Some Boom! Audio Amplifiers are not currently able to be programmed.	
PAB-1042	Y	3-24-2015	Boom! Audio Amplifier Software Issue Update
	Notes:	Informing dealers that updated Digital Tech software for programming of Boom! Audio Amplifiers will be available by 3/25/15.	
PAB-1043	Y	3-19-2015	Custom Seat Program
	Notes:	Due to an interruption of supply, the Custom Seat Program will be discontinued, effective immediately.	
PAB-1044	Y	3-19-2015	Seat Availability
	Notes:	Due to an interruption of supply, some seating products will have limited availability which may result in prolonged backorder status.	
PAB-1045	Y	4-2-2015	Low Profile Fuel Cap (62543-11) Issue
	Notes:	HD has discovered the low profile fuel cap (62543-11) has a ratcheting issue that causes the cap to be tightened too far down on the tank and can cause it to either lock to the tank or scratch the tank.	
PAB-1055 PAB-1055A	Y Y	11-3-2015 2-9-2016	Fuel Sensor and Gauge, Defective Dealer Stock
	Notes:	Requesting dealers warranty select Fuel Sensors and related Fuel Gauge Kits and to share details of the proper warranty process.	
PAB-1056	Y	11-6-2015	SE Street Performance Tuner Manufacturing Programming Issue
	Notes:	There was a manufacturing error involving the programming of some SE Street Performance Tuner kits. The affected tuners were improperly programmed yielding them inoperable with the Street Performance Tuner PC software.	
PAB-1060	Y	11-29-2016	Screamin Eagle Tuning for 2017 Trike Models
	Notes:	Clarifying the ECM tuning options for MY17 50-state US Trike models.	
PAB-1061	Y	1-6-2017	Delivery Update - 2017 Touring

	Notes:	Due to unexpected manufacturing constraints, SE Heavy Breather Billet Covers will be made obsolete/discontinued effective immediately.	
PAB-1062	Y	1-26-2017	SE Milwaukee-Eight Stage IV Kit Part Description Error
	Notes:	Notifying dealers using Talon and Lightspeed that the recently launched Milwaukee-Eight Stage IV kit part descriptions are incorrect in their DMS.	
PAB-1063	Y	3-8-2017	SE Smart Tune Pro certification Status Update
	Notes:	Notifying dealers of unforeseen certification delays for the Smart Tune PRO module.	
PAB-1064	Y	3-16-2017	HD Lock and Key Ordering Guide
	Notes:	Key style identification for parts order. all models.	
PAB-1065	Y	4-24-2017	SE Milwaukee-Eight High Flow Exhaust System Status Update
	Notes:	Updating dealers on possible fitment concerns and availability status for the Screamin' Eagle Milwaukee-Eight High-Flow Exhaust Systems.	
PAB-1066	Y	7-3-2017	Technical Publications Price Increase
	Notes:	HD will be increasing prices on technical service literature on August 23, 2017.	
PAB-1067	Y	7-31-2017	SE Smart Tune Pro
	Notes:	Smart Tune PRO - Automatic Tuning Module is 50-state U.S. EPA approved and released for shipment.	
PAB-1068	Y	9-15-2017	SE Tuner Calibration delay
	Notes:	Base calibrations are temporarily unavailable for SE Stage II, III and IV upgrades for select 2018 CVO models.	
PAB-1069	Y	11-9-2017	Screamin Eagle Upgrades for 2018 Sport Glide Not Approved For Use In California
	Notes:	Notifying California dealers of unforeseen certification delays for Stages I - IV on the 2018 Sport Glide model, FLSB, for California.	
PAB-1073	Y	5-4-2018	2018 CALIFORNIA STREET Tuner Software Compatibility Delay
	Notes:	Notifying California dealers of a delay in Street Tuner software compatibility for the 2018 XL1200NS (Iron 1200) and XL1200XS (FORTY-EIGHT Special).	
PAB-1078	Y	10-10-2018	California - Screamin Eagle Certification Status Update

	Notes:	Bulletin notifies California dealers of certification status for SE stage upgrades.	
PAB-1079	Y	10-10-2018	California - Screamin Eagle Certification Status Update
	Notes:	Bulletin notifies California dealers of certification status for SE stage upgrades.	
PAB-1081	Y	12-14-2018	Screamin Eagle Updates
	Notes:	SE Pro Street Tuner software changes related to Stage II for Trike models and Smart Tune PRO improvements.	
PAB-1083	Y	2-21-2019	2019 SOFTAIL FXDR 114 Ergonomic Alternatives
	Notes:	HD has identified alternatives to the stock riding position for riders looking for a more relaxed position.	
PAB-1084	Y	3-6-2019	Softail Backrest Pad Improvements
	Notes:	Informing dealers of design improvements for Compact Passenger Backrest Pads.	
PAB-1085	Y	3-15-2019	One Gallon Anti-Freeze Now Professional Use Only
	Notes:	Notifying dealers that one-gallon coolant/anti-freeze (99822-02) will be superseded to (99822-02A) and marked for professional use only.	
PAB-1086	Y	10-17-2019	Battery Recycling Program Update
	Notes:	Notifying dealers participating in the HD Battery Recycling Program that the pick-up process for core batteries is changing.	
PAB-1087	Y	9-20-2019	Adding Radio - FLHT BOOM! AUDIO Parts List
	Notes:	Providing dealers with the complete parts list to install a genuine Boom! Box radio in Electra Glide Standard (FLHT).	
PAB-1088	Y	1-31-2020	Lithium Batteries Application & Operation Information
	Notes:	Explaining the benefits and clarify the usage of the Lithium LiFe batteries. Dealers should also inform customers of this information prior to or at time of sale.	
PAB-1089	Y	11-8-2019	Screamin Eagle Updates
	Notes:	SE Pro Street Tuner calibrations on 2020 Touring models equipped with RDRS (Reflex Defensive Rider Systems). Software enhancement to SE Pro Street Tuner software for 2020 Touring models at WOT (Wide Open Throttle). U.S. - California: CARB (California Air Resources Board) approval on 2020 Milwaukee-Eight and Sportster SE Stage IV kits.	
PAB-1090	Y	1-9-2020	Screamin Eagle Updates

		Notes:	SE Pro Street Tuner calibrations on 2020 Touring, CVO Touring and Police models equipped with RDRS (Reflex™ Defensive Rider Systems).
PAB-1091	Y	12-3-2019	2014-LATER - BOOM! BOX GTS - Fitment Update
		Notes:	Informing dealers of the upcoming software change expanding the Boom! Box GTS radio fitment from 2019-later Touring to 2014-later Touring.
PAB-1092	Y	1-9-2020	Screamin Eagle Updates
		Notes:	CARB (California Air Resources Board) approval on 2020 Milwaukee-Eight SE kits within California.
PAB-1093	Y	8-31-2020	SE Product Updates
		Notes:	Additional SE 128/131 Stage IV Kit and 131 Crate Engine information.
PAB-1095	Y	2-12-2020	SE 4.310" Piston Oil Expander Ring Design
		Notes:	Notifying dealers of a design difference with the oil expander ring on the 4.310" piston compared to other Screamin Eagle pistons
PAB-1096	Y	2-13-2020	SE Multilayer Steel Gasket Flange Nut Torque Value Sequence Change
		Notes:	Notifying dealers of a cylinder flange nut torque value change for all SE Milwaukee-Eight stage kits utilizing a Screamin' Eagle MLS head gasket.
PAB-1097	Y	5-15-2020	BOOM Software Update
		Notes:	Software available for international order for 2014-2018 Touring models.
PAB-1098	Y	5-15-2020	New DOT 4 Brake Fluid Part Numbers
		Notes:	Providing dealers with an updated listing of replacement DOT4 brake fluid part numbers for future reference in order procurement.

PAB 1100-1199

PARTS AND ACCESSORIES BULLETINS

P&A#	PDF?	Date	Subject
1100	Y	8-4-2020 8-19-2020	Twin Cam Long Block Warranty
		Notes:	Certain twin cam longblock and twin cam warranty engines are no longer supported. Instead, shortblocks should be ordered where applicable.

1101	Y	8-14-2020	Touring models Suspension Kits - Fitment Update
	Notes:	Informing dealers of fitment update to certain suspension lowering kits.	
1102	Y	8-20-2022 8-25-2020	Softail 1/4 Fairing Mounting Post
	Notes:	Informing dealers of warranty claim issues with the mounting posts cracking.	
1103	Y Y	8-24-2020 9-4-2020	SE Stage Kit Calibration
	Notes:	Screamin' Eagle® calibrations delayed availability. This delay covers the new Touring (119/122 ci) Stage III Kits and Softail® (128/131 ci) Stage IV Kits/Crate.	
1104	Y	8-24-2020	High Flow Exhaust System
	Notes:	SE Touring High-Flow Exhaust System is now a 49-State compliant fitment for the 128/131 ci Stage IV Kit and 131ci Crate Engine.	
1105	Y	9-16-2020	SE Calibrations and Smart Tune Update
	Notes:	New Screamin Eagle calibrations are now available for 49 State application.	
1107	Y	1-4-2021 1-5-2021	P&A Vintage Parts Fitment Listing
	Notes:	Informing dealers that certain Parts and Accessories (P&A) are now being stocked at Vintage Parts, and that fitment statements for those items are at H-Dnet.com.	
1108	Y	1-5-2021 3-3-2021	Screamin' Eagle Street Tuner Update for 2021
	Notes:	Informing dealers that all Screamin' Eagle Street Tuner calibrations will have a delayed availability due to the 2021 Electronic Control Module (ECM) change on Milwaukee-Eight (MKE-8) models.	
1109	Y	1-12-2021	Screamn Eagle Stage I Components for 2021 CARB
	Notes:	Informing California dealers that Screamin Eagle Stage I products may not be installed on 2021 vehicles until California Air Resources Board (CARB) provides Executive Order (EO) approval.	
1110	Y	3-12-2021	2021 Touring / Trike Coolflow Fan Fitment

		Notes:	Original: The CoolFlow Fan is temporarily not a fitment on 2021 Touring, Trike, Custom Vehicle Operations (CVO) Touring and Police Touring motorcycles Update: Starting the week of March 15, 2021, Digital Technician II will have the updated calibrations for the CoolFlow Fan for vehicles built before 2-15-2021.
1111	Y	7-5-2022	2021 Vehicles: Screamin Eagle Updates
		Notes:	Informing dealers that Screamin Eagle® Street Tuner 49-State (only) calibrations for 2021 vehicles are now available.
1112	Y	2-19-2021	2016-2017 Dyna, 2000-2021 Softail Handlebar Fitment Updates
		Notes:	Informing dealers of the removal of some 2016-2017 Dyna, 2000-2021 Softail models from the Handlebar Fitment Guide.
1113	Y	2-23-2021	BOOM! AUDIO 30K Bluetooth Headsets
		Notes:	Boom Audio 30K Bluetooth Headsets are now able to upgrade the software to the latest Mesh 2.0 technology.
1114	Y	3-3-2021	New Gallon and 4 Liter Oil Case Quantity and Bottle
		Notes:	Informing dealers there will be a new 1 US gal and 4L case quantity and an external bottling change to the H-D 360 and SYN3 oil products.
1115	Y	3-9-2021	Handlebar Fitment Matrix Update
		Notes:	The Handlebar Fitment Matrix has been updated to include clutch cable kits for 2021 Touring fitments and timing for when the kits will be available to order and ship.
1116	Y	3-23-2021	Push-To Talk/Cruise Hand Control Kit: Fitment Update
		Notes:	Informing dealers of a no-fit situation that exists on 2021 Touring, Touring Police, CVO Touring and Trike vehicles where Citizens Band (CB) radio customers are looking to install the Push To Talk (PTT) / Cruise Hand Control Kit (71500494) to swap location of those switches.
1117	Y	3-30-2021	Screamin Eagle 2021 CARB
		Notes:	Informing California Dealers of the status of California Air Resources Board (CARB) pending approvals on 2021 Stage I-IV components/kits.
1119	Y	6-8-2021	HD AUDIO - Bluetooth Dongle & Mobile App
		Notes:	Informing dealers of the HD Audio Bluetooth Dongle for CVO customers and Harley-Davidson audio app.
1120	Y	8-27-2021	Pan America and Sportster S: Hand Grips

		Notes:	Reminding dealers to always follow the Installation Instructions and check for free rotation of throttle grip before operating vehicle. The throttle grip for 2021 Pan America vehicles (RA1250 and RA1250S) and 2021 Sportster S vehicles (RH1250S) is different from other H-D models.
1119	Y	6-8-2021	HD AUDIO - Bluetooth Dongle & Mobile App
		Notes:	Informing dealers of the HD Audio Bluetooth Dongle for CVO customers and Harley-Davidson audio app.
1123	Y	1-3-2022	Screamin Eagle Pan America Accessories - CARB
		Notes:	Four Screamin Eagle accessories for 2021 Pan America models have been granted Executive Order approval by California Air Resources Board (CARB).
1124	Y	3-4-2022	Screamin Eagle/ÖHLINS REMOTE RESERVOIR REAR SHOCKS
		Notes:	Informing dealerships that select SE Öhlins Remote Reservoir Rear Shocks (54000193) with batch number 185181, MUST NOT be installed on customer vehicles.
1125	Y	3-14-2022	Screamin Eagle Street Tuner - CARB
		Notes:	Informing dealers of Screamin' Eagle® (SE) Street Tuner software and product changes starting with 2021 vehicles. In addition, there have been two California Air Resources Board (CARB) Executive Order approvals granted for 2021 application.
1129	Y	7-19-2022	Screamin Eagle Pro Street Tuner Availability and Digital Tech
		Notes:	Screamin' Eagle Pro Street Tuner (41000008C) will be unavailable for the remainder of 2022. Pro Street Tuner availability is expected in January 2023.

[Go To Technical Menu](#)

From:

<https://sportsterpedia.com/> - **Sportsterpedia**

Permanent link:

<https://sportsterpedia.com/doku.php/techtalk:miscres:miscres06>

Last update: **2023/04/09 17:02**

