



GENUINE MOTOR PARTS AND MOTOR ACCESSORIES BULLETIN

P&A NO. 931

DATE: 04/01/2008



Michelin 150/80-16 Rear Commander Tire Update (Part Number 43252-07)

Purpose

The purpose of this bulletin is to inform you that we have become aware that in some cases the Michelin 150/80-16 rear Commander tire (Harley-Davidson Part Number 43252-07) can be challenging to mount on tubeless 3.0" wide rims. Once mounted, the tire performs as designed.

Action Requested

We recommend mounting existing inventory of the Michelin 150/80-16 rear Commander tire on tube-type applications (rims that require the use of tubes to inflate). We are working to improve the ease of mounting for this tire for tubeless application.

Questions

Please contact Technical Services with any questions regarding tire fitment.

