


1. Correct housing



2. Incorrect housing

Figure 1. Right Front Chrome Switch Housing