TT269 - October 4, 2006

## **Starter Mounting Bolts**

The torque on the starter mounting bolts for 2006 Dyna & 2007 Dyna, Softail and Touring models has changed from 13-20 ft-lbs (17.6-27.1Nm) to 18-20 ft-lbs (24.4-27.1Nm). Please change your service manuals accordingly.