SERVICE BULLETIN



M1481 2018-10-19

M1481: TOUR-PAK MOUNTING RACK SUPPORT TUBE

Purpose for Service Bulletin

This bulletin informs dealers that P&A H-D Detachables Touring Tour-Pak Rack Kit (Kit Number 53276-04A) subcomponent support tube (Part No. 53809-02) is now sold separately.

Refer to Figure 1 and Table 2. There were a number of kits produced with defective support tubes (8). These tubes only had holes on one side but should have holes on both sides. The support tubes are now warrantable items and the entire kit does not need to be returned.

Motorcycles Affected

All vehicles with Tour-Paks.

Markets Affected

All markets are affected.

Part Numbers

Refer to Table 1.

Table 1. Part Numbers

Current Part No.	Item Description	New Part No.		
N/A	Support tube	53809-02		

Required Dealer Action

If dealer finds a H-D Detachables Touring Tour-Pak Rack kit (Part No. 53276-04A) with a defective support tube, warranty the support tube only. Entire kits are not warrantable for this condition.




Figure 1. H-D Detachables Touring Tour-Pak Rack



In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service

in the interest of preserving customer sately and satisfaction, always check for outstanding recails whenever any motorcycle is brought into your dealership for earlier maintenance or service.									
ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									

Table 2. Service Parts Table

Item	Description (Quantity)	Part Number
1		Not Sold Separately
2	Nut, cap, hex lock, 1/4-20 (5)	7887
3	Washer (10)	6703
4	Spacer, rack (5)	53799-99
5	Screw, cap, hex head 1-3/4 inch (5)	Not Sold Separately
6	Screw, cap, hex head 2-1/4 inch (5)	2821
7	Plug, universal flat head (2)	Not Sold Separately
8	Tube, support, top	53809-02
9	Latch assembly (2)	50300108
10	Stud. splined (2)	Not Sold Separately