



TT445: DOT 4 BRAKE FLUID TESTER

March 19, 2015

SB-10057825-2685



APPLIES TO	SYMPTOMS
All models with DOT 4 systems	• Performance Concerns

The required service interval for changing brake fluid as stated in the maintenance schedules is every two years. A new tool, the DOT 4 Brake Fluid Tester (Part No. HD-48497-A), is available to assist in determining if fluid needs to be replaced before the required service interval.

The HD-48497-A Dot 4 Brake Fluid Tester accurately determines the brake fluid quality by measuring water contamination. Five LEDs indicate contamination level. This is a quick test that helps you promote periodic brake fluid changes with your customers. Use only with DOT4 systems.

For more information, see the Bosch Service Solution Tool web site.



Figure 1. DOT 4 Brake Fluid Tester