

2008 Touring Model Accessory Connector Location

Some early versions of the 2008 Touring Owner's Manuals (part # 99466-08) have the Accessory connector incorrectly pointed out on pages 73 and 74. Refer to the correct picture below.

In the **INCORRECT** picture the arrow is actually pointing to the GRAY data link which is under the fuse box.



Figure 21. Accessory Connector

INCORRECT

In the **CORRECT** picture the arrow points to the BLACK accessory connector located in front of the battery. This location is the same as previous years.



CORRECT